Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT IF

OIL CONSERVATION DIVISION P.O. Box 2088

	[.O. DOX 20			00
Santa	Fe,	New	Mexico	87504-2088

	•
WELL API NO.	
30-005-62475	
5. Indicate Type of Lease STATE	FEE 🗓
6 State Oil & Gas Lease No.	

DISTRICT II Santa 16, New 1910/10 P.O. Drawer DD, Artesia, NM 88210	STATE FEE A
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	K TO A 7. Lease Name or Unit Agreement Name
1 Type of Well:	Plainstec
OIL GAS OTHER	8. Well No.
2. Name of Operator Collins Oil & Gas Corporation	2
3. Address of Operator 2//3 Possue 11 NM 88202-244	9. Pool name or Wildcat Diablo-San-Andres
P.O. Box 2443, Roswell, 141	DIADIO-Sail Andres
4. Well Location Unit Letter $\underline{G}:\underline{1650}$ Feet From The \underline{North} Line and	d 2310 Feet From The East Line
10C Reser 27E	NMPM Chaves County
Section 27 10 Name of Show whether DF, RKB, RT, G	iR, etc.)
3822 GL	Jorice Report or Other Data
Check Appropriate Box to Indicate Nature of N	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	C TERRING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE	E DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TE	ST AND CEMENT JOB
OTHER: OTHER:	
12 Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent work) SEE RULE 1103.	i dates, including estimated date of starting any proposes
We propose to plug this well as follows:	. Lailorg of cement
1. Set CIBP above perforations, (2000') and dump	
on top of ping. 2.2. Cut and pull all free $4\frac{1}{2}$ " casiing estimated to	o be approx. 1596.
3. Pump the following plugs:	
35 sx 50' inside of $4\frac{1}{2}$ " stub & tag.	
25 av @ 990'-890' to cover top of queen @ 940	,1
35 sx @ $458'-358'$ to cover $8-5/8''$ stub, we wi	11 ta g this plug.
10 sx @ 30' to surface with dry hole marker.	
Thereby certify that the information above is true and complete to the true. Signature Roy H. Collins Pres.	
TYPE OR PRINT NAME ROY D. COLLINS	ТЕГЕРНОМЕ NO. 623-2040
(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS	OCT 1 7 1990
SUPERVISOR, DISTRICT II TILE	

Notify N.M.O.C.C. in sufficient time to witness