

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088  
MAY 18 1990

U. C. D.  
ARTESIA, OFFICE

WELL API NO. 30-005-62753
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Sardine
8. Well No. #1
9. Pool name or Wildcat Wildcat SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator YATES EXPLORATION CO., INC. ✓
3. Address of Operator P.O. Box "O", Albuquerque, N.M. 87103	4. Well Location Unit Letter C : 990 Feet From The North Line and 2298 Feet From The West Line Section 19 Township 9S Range 28E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3898.2	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug the well as follows:

- Set 25 sack plug TD to approximately 2235' to cover slaughter..
- Set 25 sack plug at top of San Andres from 1600' to 1700'.
- Set 25 sack plug from approximately 1160' to 1260'. 1100-1200
- Set 25 sack plug to cover base of 7" pipe from approximately 350' to 450'.
- Set 10 sack plug at surface with dry hole marker.

Notify N.M.O.C.C. in sufficient time to witness

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harvey E. Yates, Jr. TITLE President DATE May 16, 1990  
TYPE OR PRINT NAME Harvey E. Yates, Jr. TELEPHONE NO. (505)-625-0342

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 29 1990