<u>Dikir</u> a wasa			Vγ	
	OIL CONSERVATIO	N DIVISION	WELL API NO.	
DISTRICT   P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-005-62754	
DISTRICT II	Santa Fe, New Mexico	87504-2088	S. Indicate Type of Lease	
P.O. Drawer DD, Artesia, NM 88210		MR 22 '90	STATE XX FEE	
DISTRICT III		1347	6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410		0, C. D.	B-8385-2	
SHINDRY NOT	TICES AND REPORTS ON WEL	LS APPESIA, OFFICE		
( DO NOT USE THIS FORM FOR PE	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	OH PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Oil. GAS WELL XX WELL	OTHER		Amoco State	
2. Name of Operator	<u> </u>		8. Well No.	
Yates Exploration	Co., Inc.		#1	
3. Address of Operator			9. Pool name or Wildcat	
P. O. Box O Alb	uquerque, NM 87103		Diable WC Str	
4. Well Location				
Unit Letter :23	10 Feet From The South	Line and231	O Feet From The East Line	
		0.75	NIMPM Chaves County	
Section 1	Township 11S R	ange 27E	NMPM Chaves County	
	///////X	Dr, Kad, KI, CK, CC.,	<i>\(\(\(\(\(\(\(\(\(\(\(\(\(\(\(\(\(\(\(</i>	
	3753.6	Notice P	Penort or Other Data	
<del></del>	Appropriate Box to Indicate	Nature of Notice, i	SOCOURNED DEBORE OF	
NOTICE OF IN	NTENTION TO:	SUE	SSEQUENT REPORT OF:	
TOTAL DELETINA MORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK		1		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
70201721211313113		071150	Γ	
OTHER:		OTHER:		
12 Describe Personnel or Completed On	erations (Clearly state all pertinent details,	and give pertinent dates, incl	uding estimated date of starting any proposed	
eer bill 2 1103				
We pro	opose to P & A the well	In the following	g manner.	
1) Cat a 50 cack	cement plug from T.D. t	o 1930 to cover	Slaughter.	
<ol> <li>Set a 50 sack</li> <li>Tag plug &amp; fill</li> </ol>	ll hole with mud.	.0 1,50 20 00.00		
3) Set a 25 sack plug at top of San Andres 1397 (approx 1350 to 1445 ft.).				
◆4) Set a 25 sack plug at top of Queen 1137 (approx 1095 to 1190 ft.).				
5) Set a 35 sack	plug at base of Surface	casing 382 (ap	prox 330 to 455 ft.).	
6) Set a 10 sack	plug at surface & insta	ill a dry hole m	arker.	
Appro	ximate date for plugging	g is June 1, 199	U <b>.</b>	
			/	
			<i>'</i>	
I hereby cartify that the information above i	rue and complete to the best of my knowledge :	and belief.		
MM9		mr President	DATE March 20, 199	
SIGNATURE		TILE TIESTGERIC	Date -	
Harvey	E. Yates, Jr.		TELETHONE NO.	
TYPE OR PRINT NAME HATVEY				

Darrell Moore TITLE DATE 3/30/90

CONDITIONS OF APPROVAL IF ANY: Queen is at 8601