Submit 3 Copies To Appropriate District	State of New Mexi	ico ,		Form C-103
Office District I	Engray Minerals and Natural Descuraes		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION I	DIVISION	30-005-62756	£T agas
<u>District III</u> 1220 South St. Francis Dr.		is Dr.	5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			V-2328	
SUNDRY NOT	CES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Bittersweet AOZ State Com	
PROPOSALS.)			Bittersweet AC	oz state Com
1. Type of Well: Oil Well Gas Well X	Other \bigcirc	3.1562		
Oil Well Gas Well X 2. Name of Operator	/.*/		7. Well No.	
Yates Petroleum Corpo	pration / 200	s	1	
3. Address of Operator	13 200	D _{CIA} Z	8. Pool name or	
105 S. 4 th Street Arte	sia, NM 88210 (3) REGIAR	TESIA 5	North Foor Rand Foor Ranch Pre	
4. Well Location	000		roor kunch rie	-r Gillian
4. Well Location				
Unit Letter <u>J: 1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line				
	T 1: 05 D	04E ND4D!	M Chaves	County
Section 28	Township 9S Range 2 10. Elevation (Show whether DR,	26E NMP!		County
3763' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	LING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	D	ADANDONWENT
FULL ON ALTEN GAOING	COMPLETION	CEMENT JOB		
OTHER:			and commingle we	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
-				
1/22/03 – Pull RBP and commingle well. Set ASI packer with 01/off tool at 5299'.				
			AL/A C 20	NG7
Well is now commingle	d: North Foor Ranch Wolf Foor Ranch Pre-Permi	camp Oil-i	N/A Gas-20 N/A Gas-80	
	1001 Kanen He-Feiling	<i>311</i>	11/A Out 00	,,, ,
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE June TITLE Regulatory Compliance Supervisor DATE January 28, 2003				
SIGNATURE	TITLE Regulatory	Compliance Su	pervisor_DATE_	JULIUUIY 20, 2000
Type or print name Tina L. Hu	verta		Telephone	No. 505-748-1471
(This space for State use)				
	ET N SUPERVIOOR			EEB 0 6 200

APPPROVED BY Conditions of approval, if any: