	Operator Elk Oul C pany Well Jan State 12   Unit K Section 36 Township 8 API # 30-005 62763	Range <u>26</u>
	1460' Surface Plug	
848 CNC	4 Shoe Pluy 966'-1066' tas	
*2	£ 2387 -	
4882' -	4630 TOC @ 50%	
6253 -	4 5320'- TAG - Par6s	
51/2 640		

1015
Γ. Salt
B. Salt
Yates
Glorieta 2387
Delaware
Bone Sp.
Abo 4630
Wolfcamp_5320
Morrow
Devonian
Fusselman 6226
Other

TOPS

- Contact OCD 24 hrs. prior to any work done.
- of gel per barrel must be placed between each plug
- Install dry hole marker as per rule 202.B.2
- Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- Surface plug will be from 0'- 60'
- Where plugs are required cement must be placed inside and outside of all casing string(s), in the correct footage or sacks required, if no cement exists.
- Plugs to be tagged will be indicated.