Submit 3 Copies to Appropriate District Office

State of New Mexico Enea Minerals and Natural Resources Department

1CK_	
Form C-103	
Revised 1-1-89	
٧٢	

DISTRICT I

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION POR PORTO	00 01	WELL API NO.
DISTRICT II	Santa Fe, New Mexico	88 SECOVED	30-005-62780
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	Santa Pe, New Mexico	67304-2066	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		OCT -4 '90	6. State Oil & Gas Lease No. LG-8581-1
SUNDRY NOT	ICES AND REPORTS ON WE	115	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVICES (FORM C	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PE -101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: Oil. GAS WELL X	OTHER		Luce State Comm.
2. Name of Operator ELK OIL COMPANY		···	8. Well No.
3. Address of Operator			9. Pool name or Wildcat
Post Office Box 310, Rosv	vell, New Mexico 88202-(0310	Und. Foor Ranch Pre-Permian
4. Well Location Unit Letter O: 66	60 Feet From The South		10 Feet From The East Line
Olik Dedei	rea rout the	Line and 23	10 Feet From The East Line
Section 8	Township 9 South R	ange 27 East 1	NMPM Chaves County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
Chapter	Appropriate Poy to Indicate 1	Notice D	
NOTICE OF INT	Appropriate Box to Indicate I		
NOTICE OF INT	ENTION TO.	SUB:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	
12. Describe Proposed or Completed Operat	tions (Clearly state all pertinent details, as	nd give pertinent dates, includ	ing estimated date of starting any proposed
work) SEE RULE 1103.	Intend to plug and ab	oandon as follows:	
1) RI	P set @ 6200' with 35' cem	ent on ton	
2) Se	t CIDP @ 5300' with 35' c	ement on top.	it 100' plug from 5457-5357.
3) Se	et 100' plug @ 4750' Abo.	on top.	
4) Re	ecover 3800', 5½" casing.		
	t 100' plug (50 in 50 out)		
	t 100' plug @ 2486' Glorie		
	t 100' plug @ 1 536' (hase-		res.
	t 100' plug @ 400' /oto (base of 85/8)	
	t 10 sxs surface plug.		
10) Ins	stall dry hole marker and	clean up location.	
I hander marify that the information shows in terms	and complete to the heat of any beautiful	haliaf	
I hereby certify that the information above is true	and complete to the best of my knowledge and		10/00/00
SIGNATURE		Presider	nt 10/02/90
TYPE OR PRINT NAME			TELEPHONE NO.
(This space for State Use)		C . A A	2

CONDITIONS OF APPROVAL, IF ANY:

Darull Moore TITLE Diet Seal DATE 10/17/90

Notify N.M.O.C.C. in sufficient fine to tribute