

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

c/s F
lp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DEC 27 '90

WELL API NO.

30-005-62791

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

V-1548

7. Lease Name or Unit Agreement Name

Gulf State

8. Well No.

4

9. Pool name or Wildcat

Double L (Queen) Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Collins Oil & Gas Corporation

3. Address of Operator

P.O. Box 2443, Roswell, NM 88202-2443

4. Well Location

Unit Letter G : 2310 Feet From The North Line and 1980 Feet From The East Line

Section 14 Township 14S Range 29E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3752 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-23-90 Circulated hole with 8.9 lb. mud to surface. Set plugs with Class "C" Cement in the following manner with mud between all plugs.

1st plug 1850' - 1750' with 30 sx. cement.
2nd plug 940' - 840' with 30 sx. cement. Tagged plug.
3rd plug 342' - 242' with 30 sx. cement. Tagged plug.
4th plug 60' - surface with approx 20 sx. cement.

Installed dry hole marker in 8-5/8" collar. 297' of 8-5/8" cemented surface pipe left in hole. Cleaned location of trash, anchors, & filled in pits. Location ready for O.C.D. inspection.

Post ID-2
2-8-91
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy D. Collins TITLE Pres. Collins O/G DATE 12-22-90

TYPE OR PRINT NAME ROY D. COLLINS TELEPHONE NO.

(This space for State Use)

APPROVED BY Johnny Robinson TITLE INSPECTOR DATE 12-6-91

CONDITIONS OF APPROVAL, IF ANY: