

+ cist
Dp

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

DEC 4 1992

O.C.D.

WELL API NO.
30-005-62795

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG 5246

7. Lease Name or Unit Agreement Name

Pathfinder AFT State

8. Well No.
9

9. Pool name or Wildcat
Diablo Fusselman Associated

SUNDRY NOTICES AND REPORTS ON ~~WELLS~~
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER WORKOVER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter N : 660 Feet From The South Line and 2200 Feet From The West Line

Section 21 Township 10S Range 27E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3822' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Squeeze perfs, re-perforate, treat</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-22-92. TOH w/packer and two inflatable plugs at 6332' and 6364'. Set cement retainer at 6358'. Squeezed perforations 6372-6378' to 2000 psi with 140 sacks.
Set retainer at 6265'. Squeezed perforations 6295-6312' to 3000 psi w/33 sacks in formation.
Drill and clean out cement to 6350'. Sand jet 2 holes at 6300' and 2 holes at 6294'.
Acidized sand jet holes w/500 gals 15% NEFE. Swabbed well. Re-acidized sand jet holes w/500 gals 15% NEFE. Packer set at 6178'.
Well returned to production 11-7-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 12-2-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR DISTRICT II

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 10 1992