

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+
CISF
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62805
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-4914
7. Lease Name or Unit Agreement Name Runyan State Unit
8. Well No. 3
9. Pool name or Wildcat Und. Foor Ranch Pre-Permian
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3915' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator ELK OIL COMPANY
3. Address of Operator Post Office Box 310, Roswell, New Mexico 88202-0310
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>29</u> Township <u>8 South</u> Range <u>27 East</u> NMPM <u>Chaves</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Report of operations</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/01/92 through 03/15/92: Rig up pulling unit, pull out of hole with tubing and packer. Run in hole with BP, set at 5868' with 35' of cement. Perforate ABO from 5156'-5157', 5198'-5210. Run in hole with tubing and packer. Acidize with 2000 gallons 7½ NeFe. Swabbed load, blow of gas. Pull out of hole with tubing and packer, frac down casing with 48,000# of sand and 39,000 gallons gelled H2O. Run in hole with tubing. Swabbed load. Continue to swab at rate of 3 barrels of water per hour. Shut in well to evaluate.

RECEIVED

OCT - 2 1996

OIL CON. DIV.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 10/01/96
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. (505)623-3190

(This space for State Use)

ORIGINAL SIGNED BY TIM V. GUN
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE OCT 15 1996

CONDITIONS OF APPROVAL, IF ANY: