


|                            |                               |                                    |  |               |
|----------------------------|-------------------------------|------------------------------------|--|---------------|
| COMPANY<br>ELK OIL COMPANY |                               | PROPERTY NAME<br>Runyon State Unit |  | WELL NO.<br>3 |
| DATE<br>10-15-96           | LOCATION (ULSTR)<br>G-29-8-27 | FOOTAGE<br>1980 N/23 10 E          |  |               |
| API NO.<br>30-055-67205    |                               | POOL<br>Farr Ranch - Pre-Petroleum |  |               |

- 1) CIRP 5100' 10/35' CMT.
- 2) CIRP 4000' 2 1/4" casing.
- 3) Set 100' plug 20' in / 50' out casing stub at 4000' Tag.
- 4) Set 100' plug at 2 1/8" shoe; Tag.
- 5) 10' x 10' surface plug.

Plugging must be done plugs

#### CASING RECORD:



10-15-96

B6A