Submit 3 Copies to Appropriate District Office

State of New Mexico Ene. Minerals and Natural Resources Department

Form C	-103
Revised	1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe New Mexico 87504-2084

WELL API NO.	
5. Indicate Type of Lease STATE	FEE
6. State Oil & Gas Lease No.	
LG 5246	

P.O. Drawer DD, Artesia, NM 88210	8/304-2066	5. Indicate Type of Lease STATE FEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	#### + 3 1991 1	6. State Oil & Gas Lease No. LG 5246
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOIR. USE "APPLICATION FOR PI (FORM C-101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL XX WELL OTHER		Pathfinder AFT State
2. Name of Operator	48-1471	8. Well No. 13
3. Address of Operator		9. Pool name or Wildcat
105 South 4th St., Artesia, New Mexico 88	210	Diablo Fusselman Associated
4. Well Location Unit Letter F : 2310 Feet From The North	Line and1850	Feet From The West Line
Section 21 Township 10S		NMPM Chaves County
10. Elevation (Show whether 3855' GR	F DF, RRB, R1, GR, &c.	
11. Check Appropriate Box to Indicate		
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
OUNDED AND		OPNS. X PLUG AND ABANDONMENT \square
TEMPORARILY ABANDON L CHANGE PLANS	COMMENCE DRILLING	OPNS. X PLUG AND ABANDONMENT
	CASING TEST AND CE	
PULL OR ALTER CASING	1	
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103.	CASING TEST AND CE OTHER: and give pertinent dates, include	MENT JOB X ding estimated date of starting any proposed
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103. Spudded 18" hole 2:30 PM 1-27-91 with rathole NMOCD, Artesia, NM of spud. Resumed drilling Ran 23 joints 9-5/8" 36# J-55 ST&C casing set 951'. Cemented w/275 sx Howco Lite w/1/4# F1 wt. 12.7). Tail in w/150 sx "C" + 2% caC12 (casing test and ce other: and give pertinent dates, included . Drilled start: 12-1/4" hole 3:00 995'. Guide sho ocele + 5# Gilson yield 1.32, wt 14	ing hole to 40'. Notified O PM 1-28-91. De set 995', insert float set nite + 2% CaCl2 (yield 1.84, 4.8). PD 5:45 PM 1-30-91.
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103. Spudded 18" hole 2:30 PM 1-27-91 with rathole NMOCD, Artesia, NM of spud. Resumed drilling Ran 23 joints 9-5/8" 36# J-55 ST&C casing set 951'. Cemented w/275 sx Howco Lite w/1/4# F1 wt. 12.7). Tail in w/150 sx "C" + 2% caC12 (Bumped plug to 500 psi, float held okay. Cir	CASING TEST AND CE OTHER: and give pertinent dates, include Drilled start: 12-1/4" hole 3:00 995'. Guide sho ocele + 5# Gilson yield 1.32, wt 14 culated 15 sacks 5 minutes. NU a	ing hole to 40'. Notified O PM 1-28-91. De set 995', insert float set nite + 2% CaCl2 (yield 1.84, 4.8). PD 5:45 PM 1-30-91. NU and test to 2500 psi for
PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103. Spudded 18" hole 2:30 PM 1-27-91 with rathole NMOCD, Artesia, NM of spud. Resumed drilling Ran 23 joints 9-5/8" 36# J-55 ST&C casing set 951'. Cemented w/275 sx Howco Lite w/1/4# F1 wt. 12.7). Tail in w/150 sx "C" + 2% caC12 (Bumped plug to 500 psi, float held okay. Cir 10 minutes, OK. WOC. Drilled out 2:00 PM 2-1-91. WOC 32 hrs and minutes, OK. Reduced hole to 8-3/4". Resume	CASING TEST AND CE OTHER: and give pertinent dates, include Drilled start: 12-1/4" hole 3:00 995'. Guide sho ocele + 5# Gilson yield 1.32, wt 14 culated 15 sacks 5 minutes. NU a ed drilling.	ing hole to 40'. Notified O PM 1-28-91. De set 995', insert float set nite + 2% CaC12 (yield 1.84, 4.8). PD 5:45 PM 1-30-91. NU and test to 2500 psi for nd tested to 1000 psi for 5
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, work) SEE RULE 1103. Spudded 18" hole 2:30 PM 1-27-91 with rathole NMOCD, Artesia, NM of spud. Resumed drilling Ran 23 joints 9-5/8" 36# J-55 ST&C casing set 951'. Cemented w/275 sx Howco Lite w/1/4# F1 wt. 12.7). Tail in w/150 sx "C" + 2% caC12 (Bumped plug to 500 psi, float held okay. Cir 10 minutes, OK. WOC. Drilled out 2:00 PM 2-1-91. WOC 32 hrs and minutes, OK. Reduced hole to 8-3/4". Resume	casing Test and Ce other:	ing hole to 40'. Notified O PM 1-28-91. De set 995', insert float set nite + 2% CaC12 (yield 1.84, 4.8). PD 5:45 PM 1-30-91. NU and test to 2500 psi for and tested to 1000 psi for 5

ORIGINAL SIGNED, BY

MIKE WILLIAMS

... TITLE .

FEB 7 1991

CONDITIONS OF APPROVAL, IF ANY: