

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-011
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. NAME OF OPERATOR Yates Petroleum Corporation
3. ADDRESS OF OPERATOR 105 South Fourth Street, Artesia, NM 88210
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit G; 1980'FNL and 1980'FEL

RECEIVED

MAR 6 1991

O. C. D.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO. NM-42554
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME Salt Creek Unit
8. FARM OR LEASE NAME
9. WELL NO. 2
10. FIELD AND POOL OR WILDCAT Undes. W. Pecos Slope Abo
11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 1-T8S-R21E
12. COUNTY OR PARISH Chaves
13. STATE NM

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4283.5' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Request for variance ☒

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Yates Petroleum Corporation is requesting a variance be granted in requiring the BOPE and casing to be tested to 1500 psi to testing the casing to 1000 psi. The rig pump will be used to do the testing.

Yates requests this due to several reasons:

- 1) Maximum shut-in bottom hole pressure in the Abo field is between 800 psi and 1050 psi. Pressure at the surface would be less than this.
- 2) The Abo formation is such that it has to be treated before it will flow.
- 3) Rig pumps used in this area cannot safely test above 1000 psi. In order to test to higher pressures, an independent service company would have to be hired. This would result in greater expense in drilling the well.

18. I hereby certify that the foregoing is true and correct

SIGNED Clifton R. May TITLE Permit Agent

DATE 2-19-91

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FEB 23 1991

*See Instructions on Reverse Side