## Submit 3 Copies

## State of New Mexico

Form C-103	
Revised 1-1-89	ì

	.cl	51
+		On
		7

to Appropriate District Office	Energy, Minerals and Natural F	Resources Department		Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION		WELL API NO.	
DISTRICT II	P.O. Box 20 Santa Fe, New Mexico	PECEIVED	30-005-62906	
P.O. Drawer DD, Artesia, NM 88210	Santa re, New Mexico	87507-2086	5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	1	yay 6 sees	s	TATE X FEE
Diazos Ru., Aziec, INIVI 8/410		O. C. D.	6. State Oil & Gas Lease LG-4929	No.
SUNDRY NOTI	CES AND REPORTS ON WE	lister with		
DO NOT USE THIS FORM FOR PRODIFFERENT RESER (FORM C	OPOSALS TO DRILL OR TO DEEPEI RVOIR. USE "APPLICATION FOR PE -101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A ERMIT	7. Lease Name or Unit A	greement Name
. Type of Well:			-	
WEIT WEIT 1	OTHER P&A	Well	East Wind Sta	te Unit
. Name of Operator YATES PETROLEUM CORPOR	ATION $\int$		8. Well No.	
Address of Operator			9. Pool name or Wildcat	
105 South 4th St., Art	esia, NM 88210	•	Wildcat Pre-C	ambrian
	O Feet From The North	۵۵۸ د	-	II4
	rea rioni ine Holti	Line and990	Feet From The	West Line
Section 33	Township 9S R	ange 27E	NMPM Chawes	County
	10. Elevation (Show whether	•	V///	
//////////////////////////////////////		1' GR		
NOTICE OF INT	Appropriate Box to Indicate			
	ENTION TO:	SUB	SEQUENT REPO	RT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	ING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG	AND ABANDONMENT X
JLL OR ALTER CASING	_	CASING TEST AND CE		
THER:		OTHER:		
12 Describe Democrat of Complete Comple	dee (Clarker)			
<ol> <li>Describe Proposed or Completed Operat work) SEE RULE 1103.</li> </ol>	uous (Cieariy siale all pertinent details, a	na give pertinent dates, inclu	ting estimated date of starting	any proposed
TD 6517'. Reached TD	11-2-92. Plugged and	d abandoned well	as follows:	
Plug #1 6384-6284'	w/35 sx "C"	• ,		Post ID-2
<del>-</del>	w/40 sx "C"			
Plug #3 5534-5434'				7-21-95
Plug #4 4847-4747'				PXA
Plug #5 1427-1327'				<i>i * i/</i>
Plug #6 985-885'	w/40 sx		76	
Plug #7 Set 25 sx	surface plug at 60'.			
Set regulation abando	nment marker. Pluggir	ng completed 11-	3-92.	
	<b></b>	Opaccu at	- / <b></b>	
I hereby certify that the information above is true	and complete to the best of my knowledge and	l belief.		
SIONATURE Landas	Doodlett m	Production Su	pervisor	в 11-4-92
TYPE OR PRENT NAME Juanita	Goodlett	·		EPHONE NO. 505/748-14;
(This space for State Use) ORIGIN	AL SIGNED BY			
MING W	ALLIAMS			
	/ISOR, DISTRICT II m		DAT	E
CONDITIONS OF APPROVAL, IF ANY:	n Zimpo	F 11	· · · · · · · · · · · · · · · · · · ·	
, .	- a make	rield,	Nep	7-13-95
				1-15-75