

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-62911

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
VB-427

7. Lease Name or Unit Agreement Name

Hanlad AKZ State

8. Well No.
2

9. Pool name or Wildcat
Wildcat Ordovician

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter M : 330 Feet From The South Line and 1225 Feet From The West Line

Section 13 Township 8S Range 27E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3943' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Production Casing, Perforate, Treat ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 6750'. Reached TD 10-19-92. Ran 150 joints 5-1/2" 15.5# J-55 casing set 6750' Float shoe set 6750'. DV tool set 3039'. Marker joints set 6186-6209'. Cemented in two stages. Stage I - 500 sacks "H" w/8#/sx CSE + .5% CF-14 + .35% Thriftylite (yield 1.6, wt 14.0). PD 5:15 AM 10-21-92. Circulated through DV tool 4 hours. Stage II - 450 sx PSL "C" + 3% Salt + .25#/sx Celloseal (yield 2, wt 12.4). Tailed in w/100 sx "C" (yield 1.33, wt 14.8). PD 10:24 AM 10-21-92. Bumped plug to 1250 psi for 30 mins, float and casing held OK. WOC 18 hours. Drilled out DV tool at 3039'. Perforated 6396-6410' (4 SPF). Acidized perforations 6396-6410' w/1000g. 15% NEFE acid + 50 balls.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 10-28-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ DATE NOV 25 1992
CONDITIONS OF APPROVAL, IF ANY: