

457

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-62911
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VB-427

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter M : 330 Feet From The South Line and 1225 Feet From The West Line Section 13 Township 8S Range 27E NMPM Chaves County	5. Well No. 2	6. Pool name or Wildcat Paloma Mesa
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3943' GR					

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Swab test Ordovician perforations <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-15-94 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni V packer and TOOH with 2-7/8" tubing and packer. Shut down.  
9-16-94 - TIH w/RBP, packer and 2-7/8" tubing. Rigged up wireline. TIH w/1-11/16" gamma ray tool and correlated tools into place. TOOH with gamma ray tools. Set RBP at 6470' and packer at 6417'. Rigged up swab and swabbed. Shut well in. NOTE: Perforations straddled were 6427-6455'.  
9-20-94 - Bled well down and rigged up swab. Moved RBP and packer. Straddled perforations 6353-6371'. Rigged up swab. Swabbed. Put well on 1/8" choke and flow tested. Moved tools and straddled perforations 6353-6371' and swabbed. Put well on 1/8" choke and flow tested. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 9-21-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

**SUPERVISOR, DISTRICT II**

**OCT 5 1994**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_