

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-005-62960

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Hanson Operating Company, Inc.

3. Address of Operator

P.O. Box 1515, Roswell, New Mexico 88202-1515

8. Well No.

#4

9. Pool name or Wildcat

Many Gates-San Andres

4. Well Location

Unit Letter B : 1650 Feet From The East Line and 330 Feet From The North Line

Section 12

Township 9S

Range 29E

NMPM Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4004' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received Plugging Orders From Mark Ashley on 6-28-93 To P & A As Follows:

7-1-93 Ran C.B.L. Found top of cement at 1850'. Penetrated 4 SPF at 1850' & 10 3/4" csg shoe at 450'.

7-2-93 Set a 25 sx Premium Plus Cement Plug from 3189' to 3070' (TD 3189').
Set a 25 sx Premium Plus Cement Plug from 2500' to 2400' (Top of S.A. - 2445').
Set a 35 sx Premium Plus Cement Plug 50' in and 50' out from 1900' to 1800' (Top of Queen - 1938').
Set a 25 sx Premium Plus Cement Plug from 1330' to 1230' (Top of Yates - 1277').
Set a 35 sx Premium Plus Cement Plug 50' in and 50' out from 450' to 325' (10 3/4" - 7' Csg Shoe).
Tagged Plug at 325'.

Set a 10 sx Premium Plus Cement Plug at surface.

All Plugs set with mud laden fluid. Plugging witness By Ray Smith w/NMOCD.

Post ID-2
8-6-93
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Patricia A. McGraw

TITLE Production Analyst

DATE July 13, 1993

TYPE OR PRINT NAME

Patricia A. McGraw

TELEPHONE NO. 505/622-7330

(This space for State Use)

APPROVED BY

[Signature]

TITLE

Bill [Signature]

DATE

2/3/94

CONDITIONS OF APPROVAL, IF ANY: