

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO DRILL OR TO RE-OPEN OR PILE BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PURPOSES.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Klabzuba Operating Company	5b. State Oil & Gas Lease No.
3. Address of Operator Lexington Place, 930 West First Street, Fort Worth, TX 76102	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>A</u> <u>598'</u> FEET FROM THE <u>North</u> LINE AND <u>1308'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>10-S</u> RANGE <u>27-E</u> N.M.P.M.	8. Form of Lease Name White "A"
15. Elevation (Show whether DF, RT, GR, etc.)	9. Well No. 1
	10. Field and Pool, or Wildcat Race Track (Devonian)
	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/18/94: Set CIBP @ 2185'
Cut 5½" casing @ 960', casing did not part.
Cut casing at 925' and start out of hole

03/19/94: POH w/ 5½" casing
RIH w/ tubing and pump the following plugs:
10 sx @ 2185'
35 sx @ 1697'
40 sx @ 1079'
40 sx @ 429' WOC 3 hrs and tag @ 295'
10 sx @ 30' w/ dry hole marker

Location will be cleared of junk and the pits covered following NMOC rules and regulations. We will notify NMOC when everything is done.

Post FO-2
4-4-94
P4A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE AGENT DATE 3/25/94

APPROVED BY [Signature] TITLE Field Rep. #1 DATE Nov. 28-94
CONDITIONS OF APPROVAL, IF ANY: