

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NR001

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

C15F

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUEMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well: ☐ Oil Well ☒ Gas Well ☐ Other	5. Lease Serial No. NM-57255
2. Name of Operator: MARBOE ENERGY CORPORATION	6. If Indian, Allottee or Tribe Name
3a. Address: PO BOX 227, ARTESIA, NM 88211-0227	7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (including area code) (505) 748-3300	8. Well Name and No. LOBO FEDERAL #1
4. Location of Well (Footage, Sec., T., R., M., or Survey Description): 1661 FSL 2083 FWL, SEC. 33-T13S-R29E, UNIT K	9. API Well No. 30-005-63008
	10. Field and Pool, or Exploratory Area LONE WOLF ATOKA
	11. County or Parish, State CHAVES CO., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

existing perts. @ 8832' - 8842'

NOTIFY ELM 24 HRS BEFORE STARTING

1. POOH W/ RODS & TUBING 9620'
2. SET 5 1/2" CIBP @ 9600' (PERF 9686' - 9723') existing.
3. ~~SPOT 100' PLUG @ 8500' (STRAWN 8468')~~ Set CIBP @ 8782' w/ 35' cnt. on top.
4. CUT & PULL 5 1/2" CASING, TOC @ 7500'
5. SPOT 100' PLUG, 60" IN, 50" OUT, STUB WOC TAG
6. SPOT 100' PLUG @ 5050' 75'
7. SPOT 100' PLUG @ 2290' (8 5/8" SHOE @ 2240') WOC TAG
8. SPOT 100' PLUG @ 275' (13 3/8" SHOE @ 225') WOC TAG
9. SPOT 60' PLUG @ SURFACE
10. CUT OFF WELL HEAD. INSTALL DRY HOLE MARKER.

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

14. I hereby certify that the foregoing is true and correct: Name (Printed/Typed) DIANA J. CANNON		Title PRODUCTION ANALYST
Signature <i>Diana J. Cannon</i>		Date OCTOBER 31, 2002
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved by <i>RC L</i>	Title P.E.	Date 11/5/02
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office RFU