

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-63038
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-6272
7. Lease Name or Unit Agreement Name Paulette PV State
8. Well No. 5
9. Pool name or Wildcat Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter G : 2310 Feet From The North Line and 1650 Feet From The East Line Section 16 Township 5S Range 25E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3803' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Spud, resume drilling, surface casing and cement <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 26" hole with rat hole machine at 9:00 AM 1-19-95. Set 50' of 20" conductor pipe. Cemented to surface. NOTE: Notified OCD - Artesia of spud. Resumed drilling a 14-3/4" hole with rotary tools at 7:15 PM 1-20-95.

TD 907'. Reached TD at 3:30 AM 1-22-95. Ran 20 joints of 9-5/8" 36# 8rd J-55 ST&C (894.12') of casing landed at 904' with 14' landing joint. 1-Texas Pattern notched guide shoe set at 904'. Insert float set at 859'. Cemented with 500 sacks Pacemaker Lite C, 1/4#/sack celloseal, 5#/sack gilsonite and 3% CaCl₂ (yield 1.84, weight 12.7). Tailed in with 250 sacks "C" with 2% CaCl₂ (yield 1.32, weight 14.8). PD 9:15 AM 1-22-95. Bumped plug to 750 psi, OK. Circulated 170 sacks to pit. WOC. Drilled out at 3:45 AM 1-23-95. WOC 18 hours and 30 minutes. Nippled up and tested to 1000 psi for 10 minutes. Reduced hole to 8-3/4". Resumed drilling. NOTE: Centralizers used on joints #1, #3 and #5. Job witnessed by Mike Stubblefield w/OCD - Artesia.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-24-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

ORIGINAL SIGNED BY TIM W. CUM
(This space for State Use) DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 8 1995