Submit 3 Copies to Appropriate District Office

State of New Mexico Ene. 61, Minerals and Natural Resources Department

Form C-103
Revised 1-1-6

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe New Mexico 87504-2088

30-005-63051

DATE -

WELL API NO.

P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.		
	V-2982		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name		
I. Type of Well: OIL GAS WELL X WELL OTHER	Quincy AMQ State		
2. Name of Operator	8. Well No.		
YATES PETROLEUM CORPORATION	8		
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat Acme San Andres, Southeast		
4 Well Location			
Unit Letter F : 2310 Feet From The North Line and 2310	Feet From The West Line		
	NMPM Chaves County		
Section 12 IOWHERD 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3941 GR			
Check Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data		
	SEQUENT REPORT OF:		
NOTICE OF INTENTION TO:	ALTERING CASING		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			
PULL OR ALTER CASING CASING TEST AND CR			
OTHER: OTHER: Perfora			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu-	ding estimated date of starting any proposed		
work) SEE RULE 1103.			
3-14-95 - Cleaned location and set and tested anchors. Weld on bell nipple. Moved in and rigged up pulling unit. Rigged up wireline and ran CNL/GR log. TOOH with wireline. TIH with bit and scraper. Tagged PBTD at 2222'. TOOH. TIH with 4" casing guns and perforated 2162-2182' w/40 .42" holes (2 SPF). TOOH with wireline. TIH with packer to 2200'. Spotted 2 bbls acid. Nippled down BOP. Set Acidized perforations 2162-2182' with 5000 gallons 20% NEFE ac			
Flowed well down. Swabbed. Shut well in. 3-15-95 - Released packer. Nippled up BOP. TOOH. Rigged up wireling 2 Bingsth 4" casing guns and perforations 2185-2214' w/64 .42" holes (2 SPF). Tagged fill at 2214'.			
TIH with tubing. Washed down to 2222'. TOOH. Shut well 3-16-95 - Nippled down BOP. Nippled up frac valve. Acid (via 5-1/2" casing) with 10000 gallons 20% NEFE gelled ac	ized terting actual values war.		
Released well to production department.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	Clerk 3-24-95		
SIGNATURE TITLE TITLE DATE			
TYPEOR PRINT NAME Rusty Klein	<u>тецерноне но. 505/748—1</u> 4		
(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM	MAR 3 1 1995		

- TITLE -

APPROVED BY -