District Office

DISTRICT I P.O. Box 1980, Hobba, NM 88240

nt

Form C-103 Revised 1-1-89

-	State of New Mexico
Submit 3 Copies to Appropriate District Office	Energy,inerals and Natural Resources Departmen
District Office	

$\Omega \Pi = 0$	CONSER	VAT	MOM	DIV	ISIO	N C	Į
	110.30.10						

P.O. Box 2088

WELL API NO. 30-005-63061

DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	5/304-2066	5. Indicate Type of Lease STA	TE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No V-2982		
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVO (FORM C-10	ES AND REPORTS ON WEL OSALS TO DRILL OR TO DEEPEN OIR. USE "APPLICATION FOR PER 11) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agree	ement Name	
1. Type of Well: OIL GAS WELL X WELL	OTHER		Quincy AMQ	State	
2. Name of Operator YATES PETROLEUM CORPORAT	TION		8. Well No.		
3. Address of Operator			9. Pool name or Wildcat		
105 South 4th St., Artes	sia, NM 88210		Acme San Andres,	Southeast	
4. Well Location	Q 1.	165	0	West Line	
Unit Letter K : 1650	_ Feet From The South	Line and 10.30	Feet From The	West Line	
Section 12	Township 8S Ra	nge 27E	NMPM Chaves	County	
Section 12	10. Elevation (Show whether		(////		
	3934		<u> </u>		
11. Check A	ppropriate Box to Indicate I	Nature of Notice, R	eport, or Other Data		
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REPOF	IT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERI	NG CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG A	ND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C			
OTHER:		OTHER: Production casing & cement X			
12. Describe Proposed or Completed Operation work) SEE RULE 1103. TD 2221'. Reached TD at (2223.10') of casing so at 2216'. Used 25 bbls 1.34, weight 14.8). Pl Cement did not circula from 2104-2124'. Sand cement. Lost returns thad returns for 14 bbls Released rig at 10:00	at 12:45 PM 5-5-95., let at 2221'. 1-regulars of gelled water ahead 9:15 PM 5-5-95. Butte. Set slips and cublasted casing set for when shut down to dros. Lost returns with PM 5-5-95.	Ran 51 joints o ar guide shoe s ad of 350 sacks mped plug to 70 t off 5-1/2" ca rom 1516-2216'. p plug. Regain	f 5-1/2" 15.5# 8r et at 2221'. Flo Class "C" with . O psi for 3 minut as E E E Wh and returns with 3	d J-55 ST&C out collar set 5% CF-14A (yield es, OK. ther joint set mixing 2 bbls pumped. ed 52 bbls.	
Waiting on completion unit.			DIST. 2		
-	the state of the base of must be considered and	1 helief			
I hereby certify that the information above is true	and complete to the nest of my knowledge and	Production	Clark	5-16-95	
SIGNATURE TUSING	π	TE Troduction		EPHONE NO. 505/748-1471	
TYPEOR PRINT NAME Rusty Klein			1617	ZIRATE NO. 303/110 at 1.1	
(This space for State Use)	THE TAX THE WORLD			ΜΔΥ 1 9 1995	

original signed by tim W. Gum

HISTRICT II EUPERVISOR

APPROVED BY---

______ TITLE —

CONDITIONS OF APPROVAL, IF ANY: