

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-005-63071

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Hanson Operating Company, Inc.

3. Address of Operator

P.O. Box 1515, Roswell, NM 88202-1515

7. Lease Name or Unit Agreement Name

Ponderosa

8. Well No.

#2

9. Pool name or Wildcat

SE Acme San Andres

4. Well Location

Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line

Section 23 Township 8S Range 27E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3933 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-22-01 RU unit and casing equipment and nipple down wellhead, pull and lay down rods and install BOP and pull out of hole with tubing.
- 2-23-01 Go in hole w/CIBP 5 1/2" and set it at 2020', circulated well w/brine gel 9.5# mud and spotted 6 sxs cement on top of CIBP. Pull tubing to 1045' and spotted 25 sxs. Tagged at 823' pull tubing to 579' spotted 25 sxs cement.
- 2-26-01 Tag plug at 327', pull tubing up to 100' from surface and circulated cement 15 sxs to surface, dug out cellar and cut off wellhead and installed dry hole marker, cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Betsy Speer*

TITLE

Prod. Analyst

DATE 3-6-01

TYPE OR PRINT NAME

*Betsy Speer*

505-622-7330  
TELEPHONE NO.

(This space for State Use)

APPROVED BY

*Phil Hawkins*

TITLE

*Field Rep I*

DATE

*8/6/2001*

CONDITIONS OF APPROVAL, IF ANY: