dsf

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY	NOTI	CES	AND	REF	PORTS	ON	WELL	S	ا س. ا	ij		
							. پارت		1144		 - 1	7

(MM-14/33

Do not use this form for proposals to dr Use "APPLICATION FO	Ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals 3 1997	6. If Indian, Allonee or Tribe Name				
SUBMIT	7. If Unit or CA, Agreement Designation					
I. Type of Well	1					
Oil X Gas Other	8. Well Name and No.					
2. Name of Operator	Powers OL Federal Com #					
YATES PETROLEUM CORPORATION	9. API Well No.					
3 Address and Telephone No. 105 South 4th St., Artesia,	30-005-63094 10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec., T., R., M., or Survey D	Pecos Slope Abo					
•	11. County or Parish, State					
JOS TRE & 1000 THE ST. BEEFT	385' FNL & 1680' FWL of Section 33-T6S-R25E (Unit C, NENW)					
	Chaves Co., NM					
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Abandonment	Change of Plans				
	Recompletion	New Construction				
X Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off				
	Casing Repair					
Final Abandonment Notice	☐ Altering Casing X Other Perforate & frac	Conversion to Injection				
	M Other refforate a frac	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				
13. Describe Proposed or Completed Operations (Clearly state a	Il pertinent details, and give pertinent dates, including estimated date of starting					
•	cal depths for all markers and zones persinent to this work.)* set and tested anchors. Rigged up wir	eline TIH with logging				
tools and ran CBL/GR/CCL log.	3-3/8" casing ours and					
perforated 3652-3756' w/44 .3	3746-3756' (2 SPF -					
San Andres). TOOH with casir	c'd perforations					
3652-3756' with 144,350 gallo	O Brady sand. Shut well					
in for 30 minutes. Opened we	down frac valve and					
nippled up BOP. Moved in and	ating nipple and 2-3/8"					
tubing. Tagged sand at 3770'	. Washed sand down to 4018'. Pulled	up and set seating				
nipple at 3600'. Nippled dow	m BOP and nippled up wellhead. Swabb	ing.				
4-23-97 - Continue to swab.	PETER W. CORD					
4-24-97 - Continue to swab.	PETER W. CHESTER					
4-25-97 - Continue to swab.						
4-26-97 - Continue to swab. $4-27-97$ - Swab and flow test.	MAV					
4-27-97 - Swab and flow test. $4-28-97$ - Flow test. Release	MAY 7 1997					
7- 20-77 I I I W LEST. RETEAST	UREAU OF LAND					
	UREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA					
		JORCE AREA				

Conditions of approval, if any: