

AFTER

C ANY: Marbob Energy Corp.
LEASE & WELL NO. McClintock Fee 31
FORMATION: _____
COUNTY & STATE: Chaves N.M.



**DAWSON
PRODUCTION
SERVICES**

RAYMOND MALDONADO

SUPERVISOR, P & A OPERATIONS

BUS: (505)393-9171

FAX (505)393-3848

MOBILE (505)390-0540

MOBILE (505)390-0540

Spot 50' surface plug and set
P & A marker

Cement Cir.

13 3/8 400' cement. w/350 sxs cir. to surface
Spot 100' cement plug at 13 3/8 shoe 50' in and 50' out
and tag

Cement Cir.

8 5/8 1719' cement w/1025' sxs cir. to surface
Spot 100' cement plug at 8 5/8 shoe 50' in and 50' out
and tag.

Cut and pull 5 1/2 from free point and
spot 100' cement plug at stub 50' in and 50' out
and tag

Est. T.O.C. 6200'

Set 5 1/2 CBP at 6735' cap w/35' cement

5 1/2 6785' cement w/100 sxs
Open hole perf. 6785' - 6977'

Open Hole T.D. 6977'