Submit 3 Copies to Appropriate District Office	State of New M Energy, Minerals and Natural I		(\51	Form C-103
DISTRICT I				Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	(1)
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of L	005-63121
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410				STATE X FEE
1000 No Dieste Nu., Aziet, INN 8/410			6. State Oil & Gas Lo	ase No. 6274
SUNDRY NOTIO	CES AND REPORTS ON WE	LLS		
(DO NOT USE THIS FORM FOR PRODIFFERENT RESER	IVUIH. USE APPLICATION FOR PE	N OR PLUG BACK TO A	7. Lease Name or Uni	i Agreement Name
1. Type of Well:	101) FOR SUCH PROPOSALS.)			
MEIT MEIT X	OTHER	The automotive		_
2 Name of Operator YATES PETROLEUM CORPORA	MTON	/UL - 8 1897	Bee OC) State
				5
105 South 4th St., Arte	sia, NM 88210		9. Pool name or Wildo	· ·
·· · · · · · · · · · · · · · · · · ·		- 528 1 U J J		
Unit Letter ;198	O Feet From The South	Line and1400	Feet From The	East Line
Section 32	Township 5S Pa	ange 2517 s	MPM Chave	
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	IMPM Chave	S County
11. Check A	proprieto Panto I di uni	760' GR		
NOTICE OF INTENTION TO				
خے	-iviloiv 10.	SOBS	SEQUENT REP	ORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALT	ERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. DPLU	G AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEM	·	
OTHER:		OTHER: Perforate		<u>x</u>
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				
work) and note 1101.				
6-27-97 - Cleaned location, set and tested anchors. Rigged up wireline. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools. TIH with 4" casing guns and				
perforated 3778-3836' w/44 .38" holes as follows: 3778-3788' and 3826-3836' (2 SPF -				
Abo). TOOH with casing guns and rigged down wireline. Prep to frac. 6-28-30-97 - Prep to frac.				
7-1-97 - Frac'd perfora		145000 gallons	20# crosslink	gel and
400000# 16-30 Brady sand. Opened well to pit to flow well down. Moved in and rigged				
up pulling unit. Nippled down frac head and nippled up BOP. TIH with 2-3/8" tubing and seating nipple. Tagged sand at 3900'. Washed down to 4130'. Set slips and flanged up.				
Rigged down pulling un:	it. Rigged up foam ai	ir unit. Began u	unloading frac	with foam unit.
7-2-97 - Rigged down fo	oam air unit. Release	ed well to produc	ction departme	ent.
0				
I hereby certify that the information above is true, a	nd complete to the best of my knowledge and			
SIGNATURE of usty	<u> </u>	Operations Te	chnician	July 7, 1997
TYPEOR PRINT NAME Rusty Klein		ş.	1	TELEPHONE NO. 505/748-147
	ied by tim W. Gum			JUL 9 1997
DISTRICT II SU	PERVISOR mm	LB		JUL 9 1997