

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30005-63139

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:  
Twin Lakes San Andres Unit

7. Well No.  
201

8. Pool name or Wildcat  
Twin Lakes; San Andres (Assoc)

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3953GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐ Injection ☐

2. Name of Operator  
Concho Oil & Gas Corp.

3. Address of Operator  
110 W. Louisiana Ste 410; Midland, Tx 79701

4. Well Location  
Unit Letter O : 330 Feet from the South line and 1650 feet from the East line  
Section 1 Township 9S Range 28E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:

1. Notify the NMOCD Artesia District 24 hours prior to commencement.
2. Set 125' cmt plug @ 2575-2700'. WOC & tag.
3. Circ hole w/ mud.
4. ~~25~~ Set ~~100~~ cmt plug @ ~~1945~~-2015'.
5. ~~25~~ Set ~~100~~ cmt plug @ ~~1585~~-1605'.
6. ~~25~~ Set ~~100~~ cmt plug @ ~~785~~-885'.
7. Circ cmt from 173' to surface.
8. Cut off wellhead & install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 1-11-02

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE JAN 16 2002


Conditions of approval, if any:

# TLSAU #201

Lease No.: 24988      Dist. No. :      County: Chaves      Field: Twin Lakes San Andres  
 Section: 1      Twsp: 9S      Range: 28E      Unit Ltr: O      Location: 330' FSL & 1650' FEL

API No. 30-005-63139

Spud Date: 07/10/97  
 TD Date: 07/15/97  
 Comp Date: 08/16/97



Original Perf Details: P1: 2626, 28, 29, 30, 31, 32, 42, 43, 44, 47, 48, 49  
 18000 gals heated 20% acid