

State of New Mexico
Energy, Minerals and Natural Resources Department

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	
30-005-63234	
5. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
LG-939	
7. Lease Name or Unit Agreement Name	
WITZ VN STATE	
8. Well No.	
4	
9. Pool Name or Wildcat	
FOOR RANCH PRE-PERMIAN GAS	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well	
OIL <input type="checkbox"/>	GAS <input type="checkbox"/>
WELL <input type="checkbox"/>	WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	
Yates Petroleum Corporation	
3. Address of Operator	
105 South 4th., Artesia, NM 88210	
4. Well Location	
Unit Letter F	1980 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 26	Township 9S Range 26E NMPM CHAVES COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3801' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER Temporary abandonment <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-11-02- MIRU
2-12-02- Bled down; NU BOP & unset packer & RBP. POH. Dump 35' cement on top of CIBP @ 6050'. Set CIBP @ 5250'; dump 35' cement on top. TIH to 5200'. SI & SD for nite.
2-13-02- Circ hole w/ 10# mud. Test casing to 500# for 30 min - held OK. POH; lay down 2-7/8" tubing. NU & capped off well head. RD & move off location.
TEMPORARY ABANDONED - February 13, 2002.

Please see attached pressure test performed on 2-12-02. OCD - Artesia notified but did not witness.

Temporary Abandoned Status approved
until 2-13-04

I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE Operations Technician DATE 2/15/02
TYPE OR PRINT NAME Donna Clack TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep FEB 21 2002
CONDITIONS OF APPROVAL, IF ANY