BUREAU OF LAND MANAGEMENT.

SUNDRY NOTICES AND REPORTS ON WELLS IS Street
of use this form for proposals to delli or

5. Lease Serial No.

•	0011111		
	NM-	296	23

	Do not use the abandoned w	nis form for proposals to ell. Use Form 3160-3 (AF	o dri PD) fo	or such props	er and	88210-28	6. If India	ın, All	ottee or Tribe Name	
		IIPLICATE - Other Insti			sê sid		7. If Unit		Agreement, Name and/or No.	
1.	Type of Well				é	# %	-			
	Oil Well X Gas Well	Other		26.	Dr.	in AM	8. Well Name and No.			
2.	Name of Operator			4	OCD.	EIVED	Filar	ee .	AEL Federal #4	
	Yates Petroleum C	Corporation '		/63		ARTESIA	9. API W			
Ba. Address 3b. Phone No (include area code)						30-005-63252				
_	··· · · · · · · · · · · · · · · · ·	Artesia, NM 8821		505-748-	14/1		-1		ol, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description)							Undesignated 11. County or Parish, State			
	660' FSL & 660' F	WL of Section 33-1	r8s-	R26E (Unit	M, S	WSW)	11. County	or Pa	irish, State	
							C	haw	es Co., NM	
	12 CUECK AD	PPROPRIATE BOX(ES) T	Y) IN	IDICATE NA	TIDE O	E NOTICE D			· · · · · · · · · · · · · · · · · · ·	
		TROPRIATE BOA(ES) I	———				EPUKI, U	K O	HERDAIA	
	TYPE OF SUBMISSION				TYPE O	FACTION				
		Acidize		Deepen		Production (Start	/Resume)		Water Shut-Off	
	Notice of Intent	Alter Casing		Fracture Treat		Reclamation			Well Integrity	
LXI	Subsequent Report	Casing Repair		New Constructio	n 🔲	Recomplete		X	Other Perforate,	
4	Sunsequent Report	Change Plans		Plug and Abando	n 🗍	Temporarity Ab	andon		acidize & frac	
	Final Abandonment Notice	Convert to Injection	ū	Plug Back	ū	Water Disposal				
	TOOH with tubing a 2-21-2001 - Rigged CIBP at 6260'. To cement. TOOH. That follows: 5760-Penn). TOOH with Shut well in. 2-22-2001 - Straddiron control HCL aperforations with straddled perforations with perforations with	d up wireline. TI DOH. TIH with CIB IH with 4" casing -5764', 5830-5842' casing guns and r dled perforations acid. Moved tools 1100 gallons of 7 tions 5830-5842'.	II w P a gun, 5 igg 599 an -1/2	ith bailer nd set CIB s and perf 916-5926', ed down wi 0-5998'. d straddle 2% iron co idized per d straddle % iron con	and of P at 6 orate of 5938 reline of per of trol	dumped 35' 6100'. Ca d 5760-599 -5950' and e. TIH wi zed with 4 forations HCL acid. ions with forations	of ceme pped CII 8' w/276 5990-59 th packs 00 gallo 5916-599 Moved 600 gallo 5760-576	ent 3P v 5 .4 998' er a ons 50' too	on top of vith 35' of 2" holes (6 SPF - and RBP. of 7-1/2% Acidized ols and s of 7-1/2% Acidized	
4.	2-23-2001 - Flow	tested. Released	wel.	1 to produ	ction	departmen	t.			
	Name (Printed/Typed)	Printed/Typed)			CONTINUED ON NEXT PAGE:					
	Rusty Klein	. /1		Title	rations Te	<u>chniciar</u>	1			
Signature March 30, 2001										
ACCEPTED FOR RECURD FOR FEDERAL OR STATE OFFICE USE										
חחמ) DAVID R. GLASS			Title			Pate		
one erti	ditions of approval, if add Green fy that the applicant holds lega the would entitle the applicant to come	attathen (Approval of this notice or equilable title to those right	ce doe	es not warrant or the subject lease	Office					

Title 18 U.S.C. Section 1007 and Fine 49 USS Section 12/2, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitions of fauduled statement or agency of the United States any false, fictitions of fauduled statement or agency of the United States any false.

YATES PETROLEUM CORPORATION Filaree AEL Federal #2 Section 33-T8S-R26E Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

3-1-2001 - Moved in and rigged up pulling unit. Loaded tubing. Nippled up BOP. Unset packer and RBP. TOOH with tools. TIH with 10K packer with 2.25" nipple and 3-1/2" tubing. Set packer at 5598' and tested to 1000#, OK. Shut well in.

3-2-2001 - Frac'd perforations 5760-5998' (Penn) with 37500 gallons 650 40# binary with 102750# 20-40 sand. Flowed well back.

3-3-2001 - Flowed well back. Shut well in.

3-6-2001 - Flow tested. Shut well in.

3-7-2001 - Rigged up Pro Wireline. Set blanking plug. Bled well down. Released on/off tool. TOOH and laid down 3-1/2" tubing. TIH with on/off tool and 2-7/8" tubing and latched up on packer. Tested to 1000%, OK. Shut well in.


3-8-2001 - Rigged up slickline. TIH to pull blanking plug. Had 3' of fill on top of plug. Made 2 bailer runs. Recovered 3" of frac sand. Rigge dup kill truck. Get off on/off tool. Reverse circulated tubing clean. Latched back up. Swabbed tubing down. Shut well in.

3-9-2001 - Rigged up Pro Wireline. Tagged 2' high above blanking plug. Flushed tubing. Rigged up but still could not pull blanking plug. Unset packer. TOOH & got blanking plug out of packer. Shut well in.

3-10-12-2001 - TIH with packer and set packer at 5598'. Tested okay. BOP. Nippled up wellhead. Swabbed & flow tested. Shut well in. Released well to production department.

Operations Technician

March 30, 2001



RECENED AUG 13 DI

