	-		C19/	^
Submit 3 Copies To Appropriate District	bmit 3 Copies To Appropriate District State of New Mexico		- - 017 91	Form C-103
Office Office Appropriate District			U	Revised March 25, 1999
District I 1625 N. French Dr., Hohbs, NM 38240			WELL API NO.	Revised March 23, 1999
District II	strict!! OH CONSEDUATION DIVISION:		30-005-63262	1
Carried Control of the Control of th		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1000 Rio Brazes Rd., Amer. NM 37410		STATE		
District IV Santa Fe, NM 87505		6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa re. NM 87505		VO-5523	!	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other			7. Lease Name or Unit Agreement Name: Vista AVS State	
2. Name of Operator	Outer	7 3	7. Well No.	
Yates Petroleum Corpor	ation /	To see	#2	
3. Address of Operator	_ RE	CFIVED N	8. Pool name or	Wildcat
105 S. 4 th Street Artesi	a, NM 88210 📑 OCD .	ARTESIA N	$\binom{2}{5}$ Undesignated Foor Ranch	
		2014 65/	Pre Permio	ın
4. Well Location	C _S	-1. 7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		
Unit Letter F: 1980 feet from the North line and 1980 feet from the West line				
Section 21	Township 9S Range		MPM Cho	ives County
	10. Elevation (Show whether D.		z.)	 of the eight distribution of section as maked as a first section of the section of
3760' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
			SEQUENT REI	<u> </u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK ALTERING CASI	
TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE	COMMENCE DRILLING OPNS. X ABANDONMENT CASING TEST AND		
PULL OR ALTER CASING	COMPLETION	CEMENT JOB		
OTHER:		OTHER:		
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 4/2/01 – Spud 20" conductor hole at 12:15 PM. Set 40' of 16" conductor casing, cement to surface. Notified Jerry Guy with Artesia OCD of operations. 4/12/01 – Resumed drilling with rotary tool at 8:30 PM. 4/14/01 – Reached TD of 12-1/4" hole at 1110' at 1:30 PM. Ran 26 joints (1112.95') of 8-5/8" 24# J55 8R casing				
with landing joints set at 1110' 400 sxs 35:65 Poz C with 6% D2 (yld 1.32, wt 14.8). Plug down 4/15/01 – Drilled out at 3:30 Pt	. Texas Pattern guide shoe s 20, 2% S1, 1/8 pps D130 (yld 1 at 8:30 PM. Bumped plug to	et at 1110'. Inse .99, wt 12.6). Tai o 970 psi. Float h	rt float set at 106 led in with 200 sx eld. Circulated (7.6'. Cemented with s C with 2% CaCl2 68 sxs. WOC
I hereby certify that the information SIGNATURE Type or print name Susan He	TITLE E		hnician _DATE_	December 12, 2001 2 No. 505-748-1471
(This space for State use)	ORIGINAL SIGNED BY TIM W	. GUM		acc 1 0 2
APPPROVED BY Conditions of approval, if any:	DISTRICT II SUPERVISOR TITLE			DEC 18.2