

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
311 South First Avenue, NM 88210  
District III  
1040 Rio Grande Rd., Artesia, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

C15P  
OP

Form C-103  
Revised March 25, 1990

WELL API NO.

30-005-63262

5. Indicate Type of Lease

STATE ☒ FEDERAL ☐

6. State Oil & Gas Lease No.

VO-5523

7. Lease Name or Unit Agreement Name:

Vista AVS State

7. Well No.

#2

8. Pool name or Wildcat

Undesignated Foor Ranch  
Pre Permian

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter **F** : **1980** feet from the **North** line and **1980** feet from the **West** line

Section **21** Township **9S** Range **26E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3760' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: set production casing <input checked="" type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/30/01 - Reached TD at 6130' at 4:45 PM.

5/1/01 - Log well and sidewall cores. Loggers TD 6130'.

5/2/01 - Ran 145 joints (6134.03') casing set at 6130' as follows:

51 joints 4-1/2" 11.6# P-110 SB (2117.14')

94 joints 4-1/2" 11.6# P-110 MV (4016.89')

Float shoe set at 6130'. Float collar set at 6083.84'. Bottom marker set at 5081.63'. Top marker set at 4012.86'.

Cemented with 587 sxs Pecos Valley Lite with 1 pps D44 + 4 pps D42 + .2% D65 + .3% D167 + .2% D46 + .15% D13 (yld 1.42 wt 13.) Plug down at 9:00 PM. Bumped plug to 1085 psi for 5 mins. Float held. Notified Phil Hawkins with Artesia OCD of operations.

5/3/01 - Rig released at 1:00 AM.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE December 12, 2001

Type or print name Susan Herpin

Telephone No. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

DEC 18 2001

APPROVED BY [Signature] TITLE \_\_\_\_\_

DATE \_\_\_\_\_

Conditions of approval, if any: