				al <sup>s</sup>	/
Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103
District I	Energy, Minerals and Natural Resources			WELLADING	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	OV. CONCERNAL TRANSPORT			WELL API NO	
811 South First, Artesia, NM 88210 District III	OIL CONSERVATION DIVISION			<b>30-005-6328</b> 5. Indicate Typ	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505				Gas Lease No.
87505				L-6272	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10:) FOR SUCH PROPOSALS.)  1. Type of Well:				7. Lease Name or Unit Agreement Name:  Paulette PV State	
Oil Well Gas Well X	Other		<u></u>		
2. Name of Operator			-	7. Well No.	
Yates Petroleum Corpoi	<u>ration</u>	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	#6	
<ol> <li>Address of Operator</li> <li>105 S. 4th Street Artesia, i</li> </ol>	NA 00010	-	26. 12.	8. Pool name	
4. Well Location	NM 88210		<del></del>	Undesigi	nated
	dio		$\sim j_0$	<b>20</b>	
	•	outh	line and 460		West line
Section 16	Township <b>5S</b>	Range	25E	NMPM Chav	es County
	10. Elevation (Show )				County
Barris III.			5' GR	_	
11. Check A	ppropriate Box to In	dicate N			
NOTICE OF INTENTION TO: SUBSEQUENT F				EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS		ABANDONMENT ABANDONMENT		PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB		
OTHER:			OTHER: Perfor	ate acidize ar	nd frac X
Describe proposed or completed or starting any proposed work). SEE I recompilation.  10/21/00 - TIH with CBL. TOC 31 10/25/00 - Perf Penn sand from 484 10/25/00 - Spot 60 gals 7-1/2% IC 20 + balls. Spot 50 gals 7-1/2% IC HC Straddle all perfs. Swab.  11/6/00 - Frac Penn perfs 4847-497 100,000# 20/40 Ottawa sand.  11/21/00 - Perf Abo 3698-3701', 3' 11/27/00 - Spot 500 gals 7-1/2% IC gelled 7% KCL water + 313,000# 1 11/28 - 12/3/00 - Flowed back frac 12/5/00 - RD pulling unit. Release	RULE 1103. For Multip 100'. 17-4854', 4866-4870', 49 HCL over perfs 4962-49 CL over perfs 4847-4870 '8' with 95,648 gals 65Q 704-3706', 3789-3793', CHCL across Abo perfs 6/30 Brady sand. Pump all equipment. Turn we	962-4970° 78°. Straddl CO2 foa: 3806-381 3698-388 ed 2000 g	etions: Attach wellb 7, 4974-4978', 138 h ddle perfs 4962-497 le perfs 4847-4870'. med 35# gelled 7% 0', 3835-3840', 388 33'. Frac Abo perfs (als 7-1/2% HCL aho production departm	oles, .42" holes. 8'. Acidize with 1 Acidize with 120 KCL water +4250 2-3883', 50 holes, with 146.000 gals ead of pad.	oposed completion or 1200 gals 7-1/2% IC HCL 00 gals 7-1/2% IC HCL. # 100 mesh sand +
SIGNATURE LOG LA	/	TITLE	·	_	DATE <b>August 23, 2001</b>
Type or print name Susan Hei	1	-			ne No. <b>505-748-1471</b>
(This space for State use)	ORIGINAL SIGNED E DISTRICT II SUPERV	y tim y	V. GUM	гегерио	
APPPROVED BY Conditions of approval, if any:		TITLE_			AUG 2 9 20