## Submit 3 Copies to Appropriate District Office

State of New Mexico Energy \_\_nerals and Natural Resources Department

. —	•	1
	Ols	1

Form C-103 Revised 1-1-39

## DISTRICT

## OIL CONSERVATION DIVISION

	- 1	l	
VE	LL API NO.		
	30	)-005-63285	
5.	Indicate Type	of Lease STATE X	FEE
6.	State Oil & C	Jas Lease No.	
		V0-5659	

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-005-63285		
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE		
DISTRICT III	6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd., Aztec, NM 87410	V0-5659		
SUNDRY NOTICES AND REPORTS ON WELLS			
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	A 7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL GAS WELL WELL X OTHER	Canner AUF State		
2. Name of Operator YATES PETROLEUM CORPORATION	8. Weil No.		
3. Address of Operator	9. Pool name or Wildcat		
105 South 4th St., Artesia, NM 88210	Undesignated Wolfcamp		
4. Well Location	660 Wast		
Unit Letter M: 660 Feet From The South Line and	660 Feet From The West Line		
Section 30 Township 10S Range 27E	NMPM Chaves County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
3701' GR			
11. Check Appropriate Box to Indicate Nature of Notice	<del>-</del>		
NOTICE OF INTENTION TO:	UBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILI	LING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING  CASING TEST AND	CEMENT JOB		
OTHER: OTHER: Spud, surfac	OTHER: Spud, conductor, resume drilling, X surface casing & cement		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, i work) SEE RULE 1103.	ncluding estimated date of starting any proposed		
Spudded a 20" hole with rat hole machine at 1:30 PM 1-21 of 16" conductor pipe. Cemented to surface. Resumed dr tools at 8:00 AM 1-23-2001. Lost circulation at 59'. D in conductor pipe and pumped 10 yards of ready-mix. WOC w/OCD-Artesia of resuming drilling.	illing a 14-3/4" hole with rotary ry drilled to 114'. Cut window		
TD 607'. Reached TD at 6:15 PM 1-24-2001. Ran 14 joint of casing set at 607'. 1-Texas Pattern notched guide sh at 560'. Cemented with 280 sacks Poz C (65-35), 6% D-20 1.99, weight 12.6). Tailed in with 200 sacks "C" with 2 PD 12:30 PM 1-24-2001. PD 12:30 AM 1-25-2001. Cement d plug. WOC 5 hours and ran Temperature Survey and found to surface with 5 yards of Ready-Mix (per Mike Stubblefi & Welded on flow nipple. Drilled out at 8:30 PM 1-25-20 I hereby certify that the information showe that the complete to the best of my knowledge and belief.  SHONATURE  TYPEORPRINT NAME  Rusty Klein	oe set at 607'. Insert float set, 2% S1, 1/4#/sack D-29 (yield % CaCl2 (yield 1.32, weight 14.8). id not circulate. Did not land top of cement at 60'. Ready-mixed eld w/OCD-Artesia). WOC. Cut off		
(This space for State Use)	MAR 3 0 2001		
SUPERVISOR DISTRICT	THE D V CHAIL		

SUPERVISOR, DISTRICT II

APPROVED BY-CONDITIONS OF APPROVAL, IF ANY: