

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-005-63319

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

LG-0569

7. Lease Name or Unit Agreement Name:

Skink "SK" State

8. Well No.

#5

9. Pool name or Wildcat
Wildcat Basement

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South Fourth Street Artesia, NM 88210

4. Well Location

Unit Letter O : 1000 feet from the South line and 1980 feet from the East line

Section 36 Township 7S Range 25E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3595' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

12-16-00 - Spud with Franks rathole service.

12-20-00 - Finished moving in rotary tools. Spud at 6:00 am

12-22-00 - Ran 20 joints 11-3/4" 42# (908') casing set at 916.18'. Texas Pattern guide shoe set at 908'. Insert float set at 860.97'. Cemented with 400 sacks 35:65 Poz with 6% D20 + 2% Sil + .125#/sx D130 (yld 1.99, wt 12.6). Tailed in with 200 sks Class "C" + 2% Sil (yld 1.32, wt 14.86). Pressure bumped plug to 462'. Circulated 67 sacks cement WOC.

1-13-01 - Reached TD of 5498'.

1-13-01 - Ran 132 joints (5500.61') casing set at 5498' as follows: 48 joints 5-1/2" 15.5# SB (1982.5'); 84 joints 5-1/2" 15.5 # M Varnish (3517.61'). Regular guide shoe set at 5498'. Float collar set at 5457.62'. Bottom marker set at 4517.99'. Top marker set at 3538.41'. Cemented with 450 sacks Pecos Valley Lite with 4 pps D-24, 1 pps D44, .2% D65, .3% D167, .2% D46, .15% D13 (yld 1.42, wt 13). Plug down at 10:15 pm.

1-14-01 - Rig released at 2:15 am.

2-12-01 - Move in and rig up, prep to log and perf.

2-13-01 - TIH with CBL. Top cement at 3450'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE August 8, 2001

Type or print name Susan Herpin Telephone No. 505-748-1471

(This space for State use)

APPROVED BY For Record Only TITLE 361 DATE AUG 10 2001

Conditions of approval, if any: