


UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side



1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NM-3051
2. Name of Operator Yates Petroleum Corporation		6. If Indian, Allottee or Tribe Name
3a. Address 105 S. 4th St. - Artesia, NM 88210	3b. Phone No. (include area code) 505-748-1471	7. If Unit or C/A/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FEL of Section 25-T6S-R25E (Unit I, NESE)		8. Well Name and No. Hewitt IM Federal #5
		9. API Well No. 30-005-63320
		10. Field and Pool, or Exploratory Area Pecos Slope Abo
		11. County or Parish, State Chaves Co., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Perforate & frac Abo
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

3-27-2001 - Moved in and rigged up pulling unit. Loaded tubing. Nippled up BOP. Unset packer and TOOH with packer and tubing. Shut well in.

3-28-2001 - Rigged up wireline. TIH with gauge ring to 4800'. TOOH. TIH with composite bridge plug and set plug at 4800'. TOOH. TIH with 3-1/8" casing guns and perforated

3719-3977' w/43 .41" holes as follows: 3719-3724' (6 holes); 3727-3732' (6 holes); 3739-3748' (10 holes); 3812, 13, 14, 63, 72, 73, 74, 86, 87, 3933, 34, 45 & 3946' (14 holes); 3971-3977' (7 holes) (Abo). TOOH with casing guns and rigged down wireline. TIH with tubing open ended to 3980'. Shut well in.

3-29-4-2-2001 - Shut down. Prep to frac.

4-3-2001 - Spot 500 gallons of 7-1/2% iron control acid at 3980'. TOOH with tubing. Nippled down BOP and nippled up frac valve. Shut well in.

4-4-2001 - Frac'd perforations 3719-3977' (Abo) with 145718 gallons of 65Q N2 foam and 382000# 16-30 Brady sand. Opened well up and began flowing back frac.

4-5-2001 - Flowing back frac.

4-6-2001 - Flowing back frac.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Rusty Klein		CONTINUED ON NEXT PAGE:	
Signature <i>Rusty Klein</i>		Title Operations Technician	Date April 30, 2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title (Orig. SGD.) DAVID R. GLASS
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office JUL 11 2001

DAVID R. GLASS
PETROLEUM ENGINEER

RECEIVED

2001 JUL 11 AM 8:34

BUREAU OF LAND ACQUISITION
FOSWELL OFFICE

YATES PETROLEUM CORPORATION
Hewitt IM Federal #5
Section 25-T6S-R25E
Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

4-7-9-2001 - Flow tested. Shut well in.

4-10-2001 - Pumped 60 bbls down casing. Nippled down frac valve. Nippled up BOP. TIH with bit and collars and tagged up at 4690' - 110' of sand on top of composite plug. Could not circulate. Pulled bit above perforations. Shut down - waiting on air unit.

4-11-12-2001 - Shut down - waiting on air unit.


4-13-2001 - Bled well down. Moved in and rigged up air unit. TIH with bit and tagged sand at 4690'. Started blowing down casing. Air unit broke down. Shut down for repairs.

4-14-16-2001 - Circulating sand with air - cleaned out 180' of fill. Drilled out composite bridge plug at 4800' and cleaned out to 5300'. Pulled bit above perforations. Shut well in.

4-17-2001 - Finished POOH with bit and collars. TIH with packer with 1.85" on/off tool. Set packer at 3680'. Tested to 500#, OK. Nippled down BOP and nipped up wellhead. Flow tested. Shut well in.

4-18-2001 - Flow tested. Shut well in. Released well to production department.


Perforations open: 3719-3977' (Abo) and 4865-5010' (Penn)



Rusty Klein

Operations Technician

April 30, 2001



RECEIVED

2001 JUL 11 AM 8:34

BUREAU OF LAND MANAGEMENT
ROSNELL OFFICE