

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

*** AMENDED ***

Form C-103

Revised March 25, 1999

WELL API NO. 30-005-63346
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 25855
7. Lease Name or Unit Agreement Name: Willow Spring "32" State
8. Well No. 4
9. Pool name or Wildcat Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Reliance Energy, Inc.	
3. Address of Operator P.O. Box 10946, Midland, Texas	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>32</u> Township <u>4S</u> Range <u>25E</u> NMPM County <u>Chaves</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3853' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 4-30-01 Drilled to 670' - lost return - stuck pipe.
5-01-01 Worked pipe free - mixed LCM pills - reamed back to 398' - lost returns.
5-02-01 Mixed more LCM - reamed to 646' - lost returns - stuck pipe.
5-03-01 Worked pipe free - TOH. Attempted to set cement plug w/1" pipe - could not get back to bottom. TBIH w/bit - reamed to 393' w/air.
5-04-01 Reamed to 615' w/air - ;lugged bit - stuck pipe - worked free. TOH. Laying down DP.

Proposed to rig down Can-Tex Rig #1. TIH w/ 2-3/8" tbg to set cement plug in lost circulation zone @ 200'±. Set 2nd temporarily @ base of conductor pipe. Move in another drilling rig to finish drilling well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Peggy Abernathy TITLE Agent DATE 5-09-01
(915)
Type or print name Peggy Abernathy Telephone No. 683-4816

(This space for State use) **ORIGINAL SIGNED BY TIM W. GUM**
DISTRICT II SUPERVISOR

APPROVED BY BSS TITLE DATE MAY 20 2001

Conditions of approval, if any: