

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-005-63355

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG-0565

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street Artesia, NM 88210

4. Well Location
Unit Letter **N** : **660** feet from the **North** line and **1980** feet from the **West** line
Section **14** Township **5S** Range **24E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3924' GR

7. Lease Name or Unit Agreement Name:
Cobra AXK St Com

7. Well No.
#2

8. Pool name or Wildcat
Pecos Slope Abo

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: set and cement production casing <input type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

11/18/01 - Reached TD of 4205' at 5:15 PM. Run open hole logs. Logger's TD 4207'.

11/19/01 - Ran 95 joints (4217.08') of casing set at 4205' as follows:

30 joints 4-1/2" 10.5# SB (1298')

65 joints 4-1/2" 10.5# MV (2919.08')

Float shoe set at 4205'. Float collar set at 4157.09'. Bottom marker set at 3603.44'. Cemented with 350 sxs Pecos Valley Lite + 4 pps D24 + 3 pps D44 + .1% D65 + .4% D167 + .2% D46 (yld 1.45, wt 13).

11/20/01 - Plug down at 3:15 AM. Bumped plug to 1700 psi for 4 mins., held OK.

Notified Jerry Guy with Artesia OCD before starting pipe.

Rig released at 7:15 AM 11/20/01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE December 20, 2001

Type or print name Susan Herpin Telephone No. 505-748-1471

(This space for State use) **ORIGINAL SIGNED BY TIM W. GUM**
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE _____ DATE DEC 28 2001

Conditions of approval, if any: