

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-63361

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
VA-2070

7. Lease Name or Unit Agreement Name
Nevada AXN State

8. Well No.
1

9. Pool name or Wildcat
Wildcat Pre-Permian

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3779' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEREN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line
Section 4 Township 10S Range 26E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Spud, conductor, resume drilling, surface casing & cement <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 20" hole with rat hole machine at 1:45 PM 4-28-2001. Drilled to 40'. Set 40' of 16" conductor pipe. Cemented to surface. Resumed drilling a 12-1/4" hole with rotary tools at 9:00 PM 5-4-2001. Drilled to 65' and lost circulation. Mixed lost circulation pills and regained 20% returns. Drilled to 73'. Washed out - returns coming out around mouse hole and rat hole. TOOH. Cut door in conductor pipe. Welded chains on conductor to hold in place. Dumped 9 yards of ready-mix down conductor. NOTE: Notified Phil Hawkins w/OCD-Artesia.

TD 1126'. Reached TD at 7:15 AM 5-7-2000. Ran 27 joints of 8-5/8" 24# J-55 (1126.23') of casing set at 1126'. 1-Texas Pattern notched guide shoe set at 1126'. Insert float set at 1089'. Cemented with 450 sacks Poz C (65-35-6), 2% CaCl2, 1/8#/sack polyseal (yield 1.99, weight 12.6). Tailed in with 200 sacks "C" and 2% CaCl2 (yield 1.32, weight 14.8). PD 2:00 PM 5-7-2001. Bumped plug to 840#, OK. Circulated 25 sacks. WOC. Nippled up and tested to 500 psi for 10 minutes, OK. Drilled out at 9:15 AM 5-8-2001. WOC 19 hours and 15 minutes. Reduced hole to 7-7/8". Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 30, 2001

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: