

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-63362

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
VA-2070

7. Lease Name or Unit Agreement Name
Nevada AXN State

8. Well No.
2

9. Pool name or Wildcat
Foor Ranch Pre-Permian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter M : 660 Feet From The South 660 Feet From The West Line
Section 4 Township 10S Range 26E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3768' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Spud, conductor, resume drilling, surface casing & cement <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 20" hole with rat hole machine at 1:30 PM 5-31-2001. Drilled to 40'. Set 40' of 20" conductor pipe. Cemented to surface. NOTE: Notified Phil Hawkins w/OCD-Artesia of spud. Resumed drilling a 12-1/4" hole with rotary tools at 7:30 PM 6-17-2001.

TD 1114'. Reached TD at 12:15 PM 6-19-2001. Ran 27 joints of 8-5/8" 24# J-55 (1116.41' - includes landing joint) of casing set at 1114'. 1-Texas Pattern notched guide shoe set at 1114'. Insert float set at 1069'. Cemented with 400 sacks Poz C (65-35), 6% D-20, 2% CaCl₂ and 5#/sack gilsonite (yield 1.99, weight 12.6). Tailed in with 200 sacks "C" and 2% CaCl₂ (yield 1.32, weight 14.8). PD 6:50 PM 6-19-2001. Bumped plug to 718#, OK. Circulated 68 sacks. Backed out landing joint. Nippled up and tested to 500# for 15 minutes, OK. Drilled out at 2:30 PM 6-20-2001. WOC 19 hours and 40 minutes. Reduced hole to 7-7/8". Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 30, 2001
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 06 2001

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: