

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C19 F
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-63365
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-5656
7. Lease Name or Unit Agreement Name	Program AXP State
8. Well No.	1
9. Pool name or Wildcat	Wildcat Precambrian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 5 Township 10S Range 26E NMMP Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3782' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, acidize & frac <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-27-2001 - Cleaned location, set and tested anchors. Moved in and rigged up pulling unit. TIH with bit, scraper and tubing and tagged PBTD at 6035'. Circulated hole with 7% KCL water. TOOH with bit, scraper and tubing. Shut well in.

6-28-2001 - Rigged up wireline. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools. TIH with 3-1/8" casing guns and perforated 5800-5874' w/198 .42" holes as follows: 5800-5804', 5831-5834', 5838-5842', 5852-5874' (6 SPF - Penn). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Shut well in.

6-29-2001 - Set packer at 5725' and tested, OK. Acidized perforations 5800-5874' with 3300 gallons of 7-1/2% iron control HCL acid and ball sealers. Swabbed. Shut well in.

6-30-7-2-2001 - Swabbed. Loaded tubing. Released packer and TOOH with packer and tubing. Nippled down BOP and nipped up frac valve.

7-3-2001 - Frac'd perforations 5800-5874' (Penn) with 96000 gallons 65Q CO2 foam, 5000# 100 mesh sand and 100000# 20-40 Ottawa sand. Flowing well back.

CONTINUED ON NEXT PAGE:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Nov. 13, 2001

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 16 2001

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: