Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Où Jons.
N.M. DIV-Dist. 2 FORM APPRO OMB No. 1004
1301 W. Grand Avenue November
Artesia, NMS 88210 IN No. NM-17208

019	1
OVFD	
4-0135	
r 30, 2000	

(August 1999)

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well (S) Gas Well (Dither) Name of Operator Yates Petroleum Corporation Na. Address 105 S. 4th St Artesia, NM 88210 505-748-1471 Location of Well (Footage, Sec., T., R., M., or Survey Description) 1500' FNL & 1300' FWL of Section 14-T8S-R26E (Unit E, SWNW) 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R TYPE OF SUBMISSION TYPE OF ACTION			8. Well Name and No. Dorothy VO Federal #2 9. API Well No. 30-005-63376 10. Field and Pool, or Exploratory Area Undesignated 11. County or Parish, State Chaves Co., NM REPORT, OR OTHER DATA	
Notice of Intent Subsequent Report Final Abandonment Notice	 ☐ Acidize ☐ Deepen ☐ Alter Casing ☐ Fracture T ☐ Casing Repair ☐ Change Plans ☐ Plug and A ☐ Convert to Injection ☐ Plug Back 	truction Recomplete Abandon Temporarily Al	∭ \ ∑ C bandon	Water Shut-Off Well Integrity Other Production casing & cement
If the proposal is to deepen dire Attach the Bond under which to following completion of the intesting has been completed. For determined that the site is ready TD 6531'. Reacher follows: 85 joint varnished (2980.5) Float collar set Cemented with 935 D-167, .2% D-46 and plug to 1800 psi	d Operation (clearly state all pertinent details, incretionally or recomplete horizontally, give subsurface work will be performed or provide the Bond Novelved operations. If the operation results in a munal Abandonment Notices shall be filed only after final inspection.) and TD at 9:00 PM 7-10-2001. atts of 5-1/2" 15.5# sandblasts: att 6490½. Bottom marker sets att 6490½. Bottom marker sets sacks Pecos Valley Lite, 42 and .15% D-13 (yield 1.42, where for 4 minutes, OK. WOC. For w/BLM-Roswell of operation	ace locations and measured and to bo. on file with BLM/BIA. Requilitiple completion or recompletion or all requirements, including recompleted (3551.92') and sing set at 6531'. Let at 4804'. Top may all sing set at 4804'. Top may be sight 13.0). PD 1 Released rig at 2:0	iried subsequent reptins of reiried subsequent reptins in a new interval, a lamation, have been compared to the following subsequent	an permen markets and zones, ts shall be filed within 30 days form 3160-4 shall be filed once completed, and the operator has of 5-1/2" 15.5# set at 6531'. 2979'. 20% D-65, 1/10% 2-2001. Bumped
Waiting on comple	etion unit.			PECCULAR -
14. Thereby certify that the foregoing Name (Printed/Typed) Rusty Klein	ng is true and correct	Tille Operations T	echnic ia n	OCD ARTES!
Signature Hustry	THIS SPACE FOR FEDERA	Date September 30 ALOR STATE OFFICE US		
certify that the applicant holds leg which would entitle the applicant to		Title rant or the lease Office	D FOR RECC	
Title 18 U.S.C. Section 1001 and States any false, fictitious or fraudu	Fille 43 U.S.C. Section 1212, make it a crime for a client statements or representations as to any matter	within its Jurisdiction. DA	ly to make to any depi VID R. GLASS LEUM ENGINEER	

Wichield Average

2001 621 - 1 VW 3: S0

RECHAED