			- 068	•
Submit 3 Copies To Appropriate District	State of New Me	xico) Form C-103
Office District I	Energy, Minerals and Natur	ral Resources	V	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	V
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-005-63439	CT
District III	1220 South St. Fran	icis Dr.	5. Indicate Type o	T Lease FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM			5. B. Garde 6.	
	S AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS				
DIFFERENT RESERVOIR. USE "APPLICATI PROPOSALS.)	ON FOR FERMIT (FORM C-101) FO	SKSOCII	Salem	
1. Type of Well:	- · ·			
	Other		8. Well No.	
Name of Operator Yates Petroleum Corporat	ion /	On 35, 15	2. Well No.	
3. Address of Operator	1011	1920	9. Pool name or	Wildcat
I =	NM 88210	12 S	Undesignated	l Foor Ranch
		4 10	Pre-Permian N	Iorth
4. Well Location	- Co	29292 77 50		
M. 440	feet from the South lin	no and 1980	feet from the WE	est line
Unit Letter N . 660	_ leet from the th	ne and	reet from the	731 IMIC
Section 3 To	ownship 8S Range	26E NN	MPM Chave	∋s County
1	0. Elevation (Show whether D.	R, RKB, RT, GR, etc	.)	
	3783	'GR		
	ropriate Box to Indicate N	ature of Notice,	Report or Other I	Data
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REI	
PERFORM REMEDIAL WORK P	LUG AND ABANDON	REMEDIAL WOR	К 🗌	ALTERING CASING
TEMPORARILY ABANDON . C	CHANGE PLANS	COMMENCE DRI		PLUG AND ABANDONMENT
	MULTIPLE COMPLETION	CASING TEST AN	ND	
OTHER:		OTHER: Set prod	duction casing	X
Describe proposed or completed operation	ations (Clearly state all pertine	1		<u></u> -
starting any proposed work). SEE RU	LE 1103. For Multiple Comple	etions: Attach wellb	ore diagram of prop	osed completion or
recompilation.				
11/7/02 – Reached TD of 5790' of	at 11:15 AM. 5 5#	follower 41 iointe	SD (1707 (4!) OF	Sigints Mill yarn
11/8/02 - Ran 136 joints 5-1/2" 1. (4066.89'). Float shoe set at 579	5.5# casing set at 5790 as	: 10110WS: 41 JOINTS : Rottom marke	rsetat 4729' To	n marker set at
4062'. Cemented with 425 sx Pe	cos Valley Lite with additi	on build 1 41 and	100 00 - 10-15 4	M 11/9/02 Good
4002 : COMOTHOU THE 120 SET C		vestvia 1.41, wi	131. PD at 3:15 A	141 11) / / 02.
circulation throughout job. Noti	ified Van Barton with OCD	ves (yla 1.41, wi via voice mail o	f operations.	, , , , , , , , , , , , , , , , , , ,
circulation throughout job. Noti	ified Van Barton with OCD	ves (yid 1.41, wi via voice mail o	f operations.	W 11,7,02. GGGG
circulation throughout job. Noti	ified Van Barton with OCD	ves (yid 1.41, wi via voice mail o	f operations.	W 11,7,02. GGGG
circulation throughout job. Noti	ified Van Barton with OCD	ves (yia 1.41, wi via voice mail o	f operations.	W 11,7,02. GGG
circulation throughout job. Noti	ified Van Barton with OCD	ves (yid 1.41, wi via voice mail o	f operations.	W 11,7,02. GGG
circulation throughout job. Noti	ified Van Barton with OCD	ves (yid 1.41, wi via voice mail o	f operations.	W 11,7,02. GGG
	ified Van Barton with OCD	via voice mail o	f operations.	
I hereby certify that the information a	ified Van Barton with OCD	via voice mail o	f operations.	
	bove is true and complete to the	via voice mail o	f operations.	E November 13, 2002
I hereby certify that the information all SIGNATURE	bove is true and complete to the	via voice mail o	f operations. Ige and belief. Supervisor DATI	E November 13, 2002
I hereby certify that the information a SIGNATURE Type or print name Tige Huerto	bove is true and complete to the	e best of my knowled	f operations. Ige and belief. Supervisor DATI	
I hereby certify that the information at SIGNATURE Type or print name Tipe Huerto (This space for State 1987)	bove is true and complete to the	e best of my knowled	f operations. Ige and belief. Supervisor DATI	E November 13, 2002