		_									
NO. OF COPIES RECEIVED	<u></u>							Form C-103	N1 1		
DISTRIBUTION				5	en (n	15	\$1.5	Supersedes O C-102 and C-			
SANTA FE		NE	W MEXICO OI	L CONSE	RVATION	COMMISSIC	ИС	Effective 1-1-			
FILE							_				
U.S.G.S.					NOV 2	5 1968		5a. Indicate Type	e of Lease		
LAND OFFICE					140 :	10		State X	Fee		
OPERATOR	é								5. State Oil & Gas Lease No.		
								K-3446			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A D'EFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)											
1.								7. Unit Agreemen	at Name		
OIL GAS WELL WEL	L []	OTHER-	Dry Hol	le							
2. Name of Operator							8. Farm or Lease Name				
Daryl Davis /							State "B"				
3. Address of Operator								9. Well No.			
104 (Julf	Building	Midla	and, '	Texas	79 7 01		t t	<i>i</i>		
4. Location of Well								10. Field and Pa	ool, or Wildcat		
UNIT LETTER P		<u>660</u>	FROM THE	E	LINE AND _	660	FEET FROM	Wild	icat		
S S	LINE SEA	35 <u>35</u>	TOWNSHIP	3 S	RANGE	26 1	E NMPM.				
· · · · · · · · · · · · · · · · · · ·	-the, acc										
	\overline{u}	15.	Elevation (Shou) whether l	DF, RT, GR,	etc.)		12. County			
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙΙ	11111							DeBaca			
16.	Chec	k Appropriate	Box To Ind	icate N	ature of N	lotice R	eport or Oth	er Data			
NOTI		INTENTION T		Icate II			<u> </u>	REPORT OF	•		
NOTI	CE. OF	INTENTION	0.	1			0000000000		•		
PERFORM REMEDIAL WORK	٦		PLUG AND ABAN		REMEDIAL W	ORK		ALTE			
	f					DRILLING OP	NS.	PLUG	AND ABANDONMENT		
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.											
PULL OR ALTER CASING			Change / Lang		OTHER				[_]		
OTHER											
VINER				()							
17. Describe Proposed or Co		Operations (Clear	ly state all peri	tinent deta	ils, and give	pertinent d	lates, including	estimated date of	starting any proposed		
work) SEE RULE 1103.											

BII Drilled to 2030' Dumped 25 sacks cement at 2030', pulled 1261' of 7" casing, set plug at 1240', dumped 25 sacks of cement. Pulled 8" casing to 780', set plug. Dumped 25 sacks of cement, pulled 8" casing to 550', set plug, dumped 25 sacks cement. Pulled 8" casing XMM to 350' dumped 25 sacks of sement. Pulled all 8" casing. Pulled 270' of 10" casing. Left 80' of 14" casing in hole, dumped 50 sacks of cement. Set marker.

P+ A 11-20-68

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.									
SIGNED 6 C Towell	TITLE	Contractor	DATE NOV. 25, 1968						
APPROVED BY W. a. Gressett	TITLE	OIL AND GAS INSPECTOR	DEC 4 1968						

CONDITIONS OF APPROVAL, IF ANY: