

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

JUN 28 1978

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER _____

ARTESIA, OFFICE

2. Name of Operator
C.I.G. Exploration, Inc.

3. Address of Operator
P.O. Box 235, Midland, Texas 79702

4. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 18 TOWNSHIP 2-S RANGE 27-E NMPM.

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
S.E.A. 18

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)
4099.0' GR

12. County
DeBaca

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

C.I.G. Exploration, Inc. proposes to plug and abandon the S.E.A. 18 Well No. 1 on June 24, 1978, as outlined below.

- Spot 50 sx Class "C" cement plugs at 6050'-5910', 4800'-4660', 4300'-4160', 3500'-3360', 2800'-2660', and 1800'-1593'.
- Spot 10 sx Class "C" cement plug from 37' to surface. Clean location and install dry hole marker.

Note: All intervals not cemented will be filled with 10.2# mud. No casing recovery. Procedure verbally approved by W.A. Gressett, 6-23-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.E. Calache TITLE Dist. Prod. Supt. DATE 6-27-78

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 29 1978

CONDITIONS OF APPROVAL, IF ANY: