

N. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 8 1982

O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG-0393

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Flag-Redfern Oil Company	8. Farm or Lease Name State "31"
3. Address of Operator P.O. Box 2280 Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER P, 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 2-S RANGE 25-E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3899.5 GR	12. County DeBaca

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER Completion attempt in San Andres <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Formation Tops: San Andres-622', Glorieta-1330', Abo-3393', Hueco-4201'.

1. Set CIBP at 3400' with 35 feet of cement on top.
2. Cut off 4-1/2" casing at 2350'.
3. Spot 35 sx. Class "C" cement plug from 50' inside 4-1/2" casing stub to 50' above.
4. Spot 35 sx. cement plug from 1950'-2050'.
5. Set cement retainer in 8-5/8" casing at 1390'.
6. Squeeze below cement retainer with 50 sx. Class "C" cement.
7. Perforate 8-5/8" casing at 961, 64, 66, 67, 70, 71, 73, 74, 77, 78, 79, 80, 83, 84, 88, 89, 93, 94, 99, 1000.
8. Acidize

Continued on next page

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kelly J. Green TITLE Engineer DATE 2-5-82

APPROVED BY M. H. Withers TITLE OIL AND GAS INSPECTOR DATE FEB 16 1982

CONDITIONS OF APPROVAL, IF ANY:

N. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-0393	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT, FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Flag-Redfern Oil Company		8. Farm or Lease Name State "31"
3. Address of Operator P.O. Box 2280 Midland, TX 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>31</u> TOWNSHIP <u>2-S</u> RANGE <u>25-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3899.5 GR		12. County DeBaca

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Continued from Page 1

9. Swab.
10. If non-productive, set CIBP at 940' capped with 35' of cement.
11. Perforate 8-5/8" casing at 738, 39, 40, 41, 43, 44, 50, 51, 55, 56, 57, 58, 59, 60, 65, 66, 67.
12. Acidize
13. Swab test.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kelly J. Emerson TITLE Engineer DATE 2-5-82

APPROVED BY M. H. Walker TITLE Oil and Gas Engineer DATE FEB 16 1982

CONDITIONS OF APPROVAL, IF ANY:

CURRENT

PROPOSED

