

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LM 7601

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Wildcat</u>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <u>COCKRELL CORPORATION</u>		8. FARM OR LEASE NAME <u>Federal</u>	
3. ADDRESS OF OPERATOR <u>Suite 999, The Main Building, Houston, Texas 77001</u>		9. WELL NO. <u>1</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1,980' NW 1/4 Sec. 31, T10N, R19W, N.M.,</u> <u>Hidalgo County, New Mexico</u>		10. FIELD AND POOL, OR WILDCAT <u>Wildcat</u>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>SE 1/4 NE 1/4 Sec. 31</u> <u>T10N, R19W</u>	
15. ELEVATIONS (Show whether DE, RT, GR, etc.) <u>1,980' DE</u>		12. COUNTY OR PARISH <u>Hidalgo</u>	
		13. STATE <u>N.M.</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETION ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(Other) Casing test and cement job

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well spudded at 11:30 P.M., August 14, 1969, after drilling 17-1/2" hole to 384'; 12 joints of 13-3/8" 48#, S&W casing were run to 380' and cemented with 130 sacks Class H cement, with 4% gel and 2% Sodium Chloride, followed by 100 sacks Class H with 2% Sodium Chloride. Flow meter installed on flow out preventers and tested casing to 500 PSI.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Superintendent

DATE 9-3-69

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL:

ACCEPTED FOR RECORD
SEP - 5 1969
Date
ACTING District Engineer

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.