

July 23, 1971

RECEIVED

JUL 26 1971

Hobbs Wire and Supply Company  
P. O. Box 1050  
Hobbs, New Mexico 88240

C. J. T.  
Hobbs, New Mexico

Re: Claim No. 79-6080-2  
Norman R. Jones Star A Well No. 1, located in  
the NE/4 SE/4 of Section 16, Township 30 South,  
Range 14 West, NMPS, Hidalgo County, New Mexico  
Northwestern National Insurance Company of Mil-  
waukee, Wisconsin, \$30,000 Blanket Plugging Bond  
No. 2-661423

Gentlemen:


We provide a plugging bond for Mr. Norman R. Jones  
who has plugged a well in New Mexico in a manner which  
is not acceptable to the Oil Conservation Commission.

We are enclosing herewith a copy of the Order from the  
Oil Conservation Commission dated March 23, 1971 in-  
cluding specifications for proper plugging of this  
well. We also enclose photo copies of Well Completion  
Report dated May 25, 1971 indicating how the dry hole  
was actually plugged.

We are advised that it will be necessary to replug this  
well in accordance with the Order, and we would apprec-  
iate your advice as to whether or not you can handle  
this matter for us, and if so, what the cost will be.

Thanking you for your early attention, we are

Yours very truly,

  
A. J. Reinhardt, Manager  
Arkansas Branch Claims

KSR/jc

✓cc: Bill Cressett, Supervisor  
District 2, Oil Conservation Commission  
Prater RD  
Artesia, New Mexico  
cc: Norman R. Jones

# NORTHWESTERN NATIONAL INSURANCE GROUP

LITTLE ROCK BRANCH: P.O. BOX 9370 / LITTLE ROCK, ARKANSAS 72209 / PHONE (501) 562-5880

July 22, 1971

RECEIVED

JUL 26 1971

Chase Well Service  
P. O. Box 637  
Artesia, New Mexico 82210

D. C. C.  
ARTESIA, OFFICE

Re: Claim No. 79-6080-D  
Norman R. Jones State A. Well No. 1, located in  
the NE/4 SE/4 of Section 16, Township 30 South,  
Range 14 West, NMPH, Hidalgo County, New Mexico  
Northwestern National Insurance Company of Mil-  
waukee, Wisconsin, \$10,000 Blanket Plugging Bond  
No. S-661423

Gentlemen:

We provide a plugging bond for Mr. Norman R. Jones  
who has plugged a well in New Mexico in a manner which  
is not acceptable to the Oil Conservation Commission.

We are enclosing herewith a copy of the Order from the  
Oil Conservation Commission dated March 23, 1971 in-  
cluding specifications for proper plugging of this  
well. We also enclose photo copies of Well Completion  
Report dated May 25, 1971 indicating how the dry hole  
was actually plugged.

We are advised that it will be necessary to replug this  
well in accordance with the Order, and we would apprec-  
iate your advice as to whether or not you can handle  
this matter for us, and if so, what the cost will be.

Thanking you for your early attention, we are

Yours very truly,

K. S. Reinhardt, Manager  
Arkansas Branch Claims

KSR/jc

✓cc: Bill Gressett, Supervisor  
District 2, Oil Conservation Commission  
Drawer DD  
Artesia, New Mexico  
cc: Norman R. Jones