NO. OF COPIES RECEIVED		•	Form C-103		
DISTRIBUTION		Service Committee Committe	Supersedes Old C-102 and C-103		
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65		
FILE .					
U.S.G.S.		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5a. Indicate Type of		
LAND OFFICE			State X	Fee	
OPERATOR			K-6416	5. State Oil & Gas Lease No. K-6416	
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSALS TO D USE "APPLICATION FOR PER					
I. OIL GAS OTHER-	Dry hole		7. Unit Agreement N	ame	
2. Name of Operator	8. Farm or Lease No	8. Farm or Lease Name			
Powers Operating Co.			New Mexico	New Mexico State	
3. Address of Operator	9. Well No.	9. Well No.			
1816 Guaranty Bank Plaza	111				
4, Location of Well	Wildcat	10. Field and Pool, or Wildcat Wildcat			
UNIT LETTER			7777777 MOH 1 1	THITTINI	
THE East LINE, SECTION 4 TOWNSHIP 26S RANGE 17W NMPM			_NMPM.		
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	MATTA	
	4372'(ungrade	d ground)	Hidalgo		
Check Appropria		ature of Notice, Report	or Other Data		
NOTICE OF INTENTIO	10.	30036	QUENT REPORT OF.		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND	ABANDONMENT X	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
		OTHER			
ОТНЕЯ			·		
17. Describe Proposed or Completed Operations (Cowork) SEE RULE 1103.	learly state all pertinent deta	ails, and give pertinent dates, in	ncluding estimated date of star	rting any proposed	
12¼" hole was drilled to	505' and 500'	of 8-5/8",K-55,2	24# surface cas:	ing was	
set; casing seat @ 505'	(KB). Cement w	as circulated to	the surface.		
7-7/8" hole was drilled t				4007'.	
Reached TD on 12-1-72.					
Plugged and abandoned su	biect well on	12-3-72 as follo	ows:		
Plug #1: 3490' to 3380' 35 sacks class "A" cement					
Plug #2: 2000' to 1900' 35 sacks class "A" cement					
Plug #3: 1000' to 900' 35 sacks class "A" cement					
Plug #4: 550' to 450' 35 sacks class "A" cement					
	10 sacks cla				
			and also be	ochnicus	
The above plugs were set				=cmrrque.	
9.0 ppg mud was left in t			enc prugs.		
Welded on steel plate and	l installed dry	hole marker.			
18. I hereby certify that the information above is to	rue and complete to the best	of my knowledge and belief.			

THE Petroleum Engineer

TITLE _____ OAL AND G.S MSPECTUR

AUG 9 1973

Gene N. Garnett