

PLUGS AND ADAPTERS

Heaving plug—Material Length Depth set

Adapters—Material Size

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
		Not shot				

TOOLS USED

Rotary tools were used from 4561 feet to 8050 feet, and from feet to feet

Cable tools were used from Surface feet to 4561 feet, and from feet to feet

DATES

April 17, 1951 Put to producing Dry hole, 19.....

The production for the first 24 hours was barrels of fluid of which % was oil; % emulsion; % water; and % sediment. Gravity, °Bé.

If gas well, cu. ft. per 24 hours Gallons gasoline per 1,000 cu. ft. of gas

Rock pressure, lbs. per sq. in.

EMPLOYEES

J. J. Scarborough, Driller Jack Skaggs, Driller

John Montgomery, Driller G. C. Hendrickson, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	70	70	Brown lime
70	214	144	Sand and lime
214	455	241	Red sand and shale
455	595	140	Gyp & dolomite
595	1170	575	Lime, red sand & anhy.
1170	1235	65	Anhy., sand and shale
1235	1405	170	Lime, red shale and red sand
1405	1660	255	Red sand, shale and anhy.
1660	1995	335	Lime, red sand and anhy.
1995	2110	115	Anhy., red sand and red shale
2110	2320	210	Lime, red sand and shale
2320	2520	200	Red sand, red shale and gray shale
2520	2885	365	Salt and red sand
2885	2930	45	Brown lime
2930	3190	260	Salt
3190	3230	40	Brown lime
3230	3410	180	Salt and red sand
3410	3470	60	Brown lime
3470	3580	110	Shale, lime, anhy., sand
3580	3770	190	Salt
3770	4075	305	Salt and red sand
4075	4455	380	Red sand and salt
4455	4500	45	Dolomite, anhy., shale
4500	4800	300	Red shale
4800	5530	730	Granite wash, shale and lime