

Mr Cecil Johnson:  
Chapman Mm.

L. D. Strickland  
Box 56 Corona, N. M.

Dear Sir:

In regard to plugging the water well which you referred to, I am fixing it up to use as a water well. I have a steel storage tank, material for a wind mill tower at the well, and am going to fix it up as soon as possible.

I really don't know just how much water is in the well; possibly enough for stock use. I believe the hole is about 700 feet don't know for sure.

yours Truly.

L. D. Strickland.