

C
I
L
I
T
YO
U
R
SU
A
R
T
E
R

H
O
U
R
S

Name B. W. Weaver Date 7-11-81 ⁷⁻¹²⁻⁸¹ Miles 175 District 2
Time of Departure 1:30 PM Time of Return 10:30 AM Car No. 654A

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature _____

D

21

1 well Sec 25-19-10 Terra of New Mexico INC Riley #1
Plug to Abandon Drill Pipe @ 1836 Churned out to 1761 Set 50 SX
Class C Plug @ 1761 to 1637. Set 75 SX class C Plug @ 1604
Tag @ 754 Pumped 50 SX sand Tag @ 554, Pumped 35 SX
Sand Tag @ 554, Pump 15 SX sand Tag @ 554 Dropped
1 1/2 yd. Pin Gravel Plugged Back to 120 ft Circulated 60 SX class
C Plug from 120 ft to Surface